

ANNUAL SURVEYS.

18346

36.000
Refd 12.5.77-

No. in g. Book. on the 645 No. 15861 Survey held at London Date, first Survey 8/5/77 Last Survey 10 May 1877
"Amana" Master Becker
 Tonnage 299, 1275, 1229 Built at Glasgow When built 1875 - 7 mo
 By whom built Stephen Owners J. Smith
 Port belonging to Glasgow Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Canal dock

Last Survey, No. 15861 Port of Iron Classed 100 A.1. 2-76
 Present Condition of the Good
 Decks Good Breasthooks and Stemson Good
 Transoms, Pointers, and Crutches Good
Timbers of the Frame at the Openings Good
Ditto ditto at other places Good
 Keelsons Good
 Clamps and Shelves Good
 Ceiling Good
 Rudder Good
Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Windlass and Capstan Good
 Pumps Good
 Boats 5-12
 Masts, Yards, &c. Good
 Condition, how ascertained from the deck
 Sails Good
 Anchors, No. of 3 B. 1 S. 2 K.
 Cables part seen Good
 Hawseers and Warps Good
 Standing and Running Rigging Good
 Cargo and Main Hatchways Good Hatches Good
 Observations, Opinion as to Class, &c. Ship with a portion of cargo on board. Scraped and painted; also done close ceiling inside. It is in good condition and is eligible in my opinion to remain as classed. Reg. 100 A.1.
 Committee's Minute 22nd May 1877
 Character assigned 100 A.1
 Surveyor to Lloyd's Register of British and Foreign Shipping. J.W. Sullard
 Certificate (if required) PAID 18

No. in g. Book. on the 207 No. 16997 Survey held at London Date, first Survey 9/5/77 Last Survey 10 May 1877
"Oriana" Master Guthrie
 Tonnage 997, 997, 918 Built at Greenock When built 1864 - 2 mo
 By whom built Scott Owners W. Orr
 Port belonging to Greenock Destined Voyage ✓
 If Surveyed Afloat or in Dry Dock Canal dry dock

Last Survey, No. 16997 Port of Iron Classed *A.1. 8-76
 Present Condition of the Good
 Decks Good Breasthooks and Stemson Good
 Transoms, Pointers, and Crutches Good
Timbers of the Frame at the Openings Good
Ditto ditto at other places Good
 Keelsons Good
 Clamps and Shelves Good
 Ceiling Good
 Rudder Good
Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Windlass and Capstan Good
 Pumps Good
 Boats Good
 Masts, Yards, &c. Good
 Condition, how ascertained from the deck
 Sails Good
 Anchors, No. of 3 B - 1 S - 2 K
 Cables Large portion seen Good
 Hawseers and Warps Good
 Standing and Running Rigging Good
 Cargo and Main Hatchways Good Hatches Good
 Observations, Opinion as to Class, &c. Surveyed with a large portion of cargo on board. Bottom cleaned and painted. Rudder bushed. This ship is now in good condition and fit in my opinion to remain as classed. Reg. *A.1.
 Committee's Minute 22nd May 1877
 Character assigned *A.1
 Surveyor to Lloyd's Register of British and Foreign Shipping. J.W. Sullard
 Certificate (if required) PAID 18