

ANNUAL SURVEYS.

No. in Reg. Book. 104 No. 1 Survey held at London Date, first Survey 11 April Last Survey 12 May 1877
 on the "Old Kensington" Master Marwood
 Tonnage 137 3/4 Built at Lpool When built 1874 10 mo.
 By whom built Potter Owners Smith, Bilbrough & Co
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Hatchers dock

Last Survey, No. 16669 Port of Iron Classed 100A1 Years assigned. 7-76 Character in Register Book.
 Present Condition of the Decks
 Waterways
 Comings
 Upper Deck Beams & Fastenings
 Lower Deck Beams & Fastenings
 Planksheers
 Sheerstrakes
 Topsides
 Wales
 Plank (Bottom) and Counter
 Engine Room Skylights
 General Observations, Opinion as to Class, &c.
 Breasthooks and Stemson de de
 Transoms, Pointers, and Crutches de de
 Timbers of the Frame at the Openings de de
 Ditto ditto at other places de de
 Keelsons de de
 Clamps and Shelves de de
 Ceiling de de
 Rudder de de
 Copper or Y.M. ✓ When put on ✓
 Caulking of Bottom, Deck, & Waterways
 Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c. Good
 Condition, how ascertained
 Sails and
 Anchors, No. of
 Cables complete
 Hawseers and Warps
 Standing and Running Riggings
 Scuppers
 Cargo and Main Hatchways
 Hatches

Bottom cleaned and recoated. This ship appears eligible to remain as classed.
Surveyed with ballast in hold.

Committee's Minute 22nd May 1877 Thos Congdon
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid 18

No. in Reg. Book. 279 No. 1 Survey held at London Date, first Survey 11 April Last Survey 4 May 1877
 on the "Carpathian" Master Berry
 Tonnage 1444 Built at Hull When built 1874 9 mo.
 By whom built 1375 Humphreys Owners Mr Diamond, Greenfield & Co
 Port belonging to Lpool Destined Voyage
 If Surveyed Afloat or in Dry Dock Lincolns dock

Last Survey, No. 13735 Port of Iron Classed 100A1 Years assigned. 12-74 Character in Register Book.
 Present Condition of the Decks
 Waterways
 Comings
 Upper Deck Beams & Fastenings
 Lower Deck Beams & Fastenings
 Planksheers
 Sheerstrakes
 Topsides
 Wales
 Plank (Bottom) and Counter
 Engine Room Skylights
 General Observations, Opinion as to Class, &c.
 Breasthooks and Stemson de de
 Transoms, Pointers, and Crutches de de
 Timbers of the Frame at the Openings de de
 Ditto ditto at other places de de
 Keelsons de de
 Clamps and Shelves de de
 Ceiling de de
 Rudder de de
 Copper or Y.M. ✓ When put on ✓
 Caulking of Bottom, Deck, & Waterways
 Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c. Good
 Condition, how ascertained
 Sails and
 Anchors, No. of
 Cables complete
 Hawseers and Warps
 Standing and Running Riggings
 Scuppers
 Cargo and Main Hatchways
 Hatches

Bottom cleaned and recoated. An additional stiffening bar fitted to the Starboard of main mast. This ship appears eligible to remain as classed.
Surveyed with port antwork cargo on board.

Committee's Minute 22nd May 1877 Thos Congdon
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid 18

Old Kensington
Carpathians



© 2019

Lloyd's Register
Foundation