

18413

Rec^d 18/5/27

J. C. S. { W. M. D. 7
 Messrs 51153
 Official Number

Engine Room

If Surveyed Afloat or in Dry Dock Afloat - in Dry dock.

Character in Register Book.

BA

Dariusz Kępcio

Now close an account of damage to the
and fourth frames forward of main
of below hold beam stringer, in Starboard
way of fracture. Two plates, amidships,
then broke, on same side, removed
The whole of the damage being

Cause of Repairs to be clearly stated.

General Observations, Opinion as to Class, &c.

This vessel is now in good condition
and eligible in my opinion to remain as chartered.

(Travelling Expenses, if any, £)

Character assigned

TRM *Dep 77*

Surveyor to Lloyd's Register of British and Foreign Shipping

© 2019
Lloyd's Register
Foundation

IRAN471 - 0545