

24/5/77

18463  
ANNUAL SURVEYS.

No. in Reg. Book. *23 Sep* No. *25378* Survey held at *Liverpool* Date, first Survey *May 3<sup>rd</sup>* Last Survey *May 7<sup>th</sup>* 1877  
on the Ship *"Charles Cotesworth"* Master *Browse*  
Tonnage *1031* Built at *Liverpool* When built *1876 - 4 mo.*  
By whom built *Rogden* Owners *Cotesworth Lyne & Co.*  
Port belonging to *Liverpool* Destined Voyage  
If Surveyed Afloat or in Dry Dock *Queens Dry Dock*

Last Survey, No. *16530* Port of *Lon* Classed *100 AI*  
Present Condition of the Decks *Good* Treonails *Rivets* *Good*  
Waterways *"* Breasthooks and Stems *"*  
Comings *"* Transoms, Pointers, and Crutches *"*  
Upper Deck Beams & Fastenings *"* Timbers of the Frame at the Openings *"*  
Lower Deck Beams & Fastenings *"* Ditto ditto at other places *"*  
Planksheers *"* Keelsons *"*  
Sheerstrakes *"* Clamps and Shells *"*  
Topsides *"* Ceiling *"*  
Wales *"* Rudder *"*  
Plank (Bottom) and Counter *"* Copper or Y.M. Cement When put on *76*  
Engine Room Skylights *✓* Coal Bunker, Openings, Lids, &c. *✓* Scuppers *Good* Cargo and Main Hatchways *Good* Hatches *Good*  
General Observations, Opinion as to Class, &c.

*Bottom sighted, cleaned and coated with paint -*  
*This vessel being in a good and efficient condition*  
*is eligible in my opinion to remain as Classed -*

Committee's Minute *Liverpool May 25<sup>th</sup> 1877* *T. Shilston.*  
Character assigned *100 AI* *BS*  
Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required) Paid 18

No. *"* Survey held at *Liverpool* Date, first Survey *Apr 20<sup>th</sup>* Last Survey *Apr 23<sup>rd</sup>* 1877  
No. in Reg. Book. *704* on the Ship *"Aminta"* Master *N. Meyer*  
Tonnage *1110* Built at *Liverpool* When built *1862 - 2 mo.*  
By whom built *Jones* Owners *J. Smay & Co.*  
Port belonging to *Liverpool* Destined Voyage *India*  
If Surveyed Afloat or in Dry Dock *Queen's Dry Dock*

Last Survey, No. *16113* Port of *Lon* Classed *S.S. Liv. No 3-74*  
Present Condition of the Decks *Good* Treonails *Rivets* *Good*  
Waterways *"* Breasthooks and Stems *"*  
Comings *"* Transoms, Pointers, and Crutches *"*  
Upper Deck Beams & Fastenings *"* Timbers of the Frame at the Openings *"*  
Lower Deck Beams & Fastenings *"* Ditto ditto at other places *"*  
Planksheers *"* Keelsons *"*  
Sheerstrakes *"* Clamps and Shells *"*  
Topsides *"* Ceiling *"*  
Wales *"* Rudder *"*  
Plank (Bottom) and Counter *"* Copper or Y.M. Cement When put on *64*  
Engine Room Skylights *✓* Coal Bunkers, Openings, Lids, &c. *✓* Scuppers *Good* Cargo and Main Hatchways *Good* Hatches *Good*  
General Observations, Opinion as to Class, &c.

*Bottom sighted, cleaned and coated with paint -*  
*This vessel being now in a good and efficient condition*  
*is eligible in my opinion to remain as Classed -*

Committee's Minute *Liverpool May 25<sup>th</sup> 1877* *T. Shilston.*  
Character assigned *\* AI* *BS*  
Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required) Paid 18



"Charles Botesworth"

"Aminta" 25348



© 2019

Lloyd's Register  
Foundation