

# ANNUAL SURVEYS.

No. in Reg. Book. **65** No. **15972** Survey held at **London** Date, first Survey **11 May** 1877 Last Survey **11 May** 1877  
 on the **Le Yacht "Pandora"** Master **J. Penn**  
 Tonnage **76,316,312** Built at **P. Glasgow** When built **1870 - 4<sup>th</sup> mo**  
 By whom built **Blackwood** Owners **J. Penn**  
 Port belonging to **London** Destined Voyage **✓**  
 If Surveyed Afloat or in Dry Dock **✓**

Last Survey, No. **15972** Port of **London** Classed **S.S. Lon 12.1.76**  
 Present Condition of the Decks **good**  
 Waterways **good**  
 Comings **good**  
 Upper Deck Beams & Fastenings **good**  
 Lower Deck Beams & Fastenings **good**  
 Planksheers **good**  
 Sheerstrakes **good**  
 Topsides **good**  
 Wales **good**  
 Plank (Bottom) and Counter **good**  
 Engine Room Skylights **good** Coal Bunker, Openings, Lids, &c. **good** Scuppers **good** Cargo and Main Hatchways **good** Hatches **good**  
 General Observations, Opinion as to Class, &c. **Yacht placed in dry dock, bottom cleaned and painted. She is in good condition and eligible to remain as classed Reg. \*A.1.**

Committee's Minute **5th June, 1877**  
 Character assigned **\*A.1.**  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **✓** Paid **18**

No. in Reg. Book. **250** No. **13654** Survey held at **London** Date, first Survey **28/5/77** Last Survey **30<sup>th</sup> May** 1877  
 on the **L. Stephens** Master **Glass**  
 Tonnage **462,1535/1582** Built at **Greenock** When built **1874 - 11 mo**  
 By whom built **Steel** Owners **J. J. Greenessons**  
 Port belonging to **Greenock** Destined Voyage **✓**  
 If Surveyed Afloat or in Dry Dock **Canal dry dock.**

Last Survey, No. **13654** Port of **London** Classed **100 A.1. 12.74**  
 Present Condition of the Decks **good**  
 Waterways **good**  
 Comings **good**  
 Upper Deck Beams & Fastenings **good**  
 Lower Deck Beams & Fastenings **good**  
 Planksheers **good**  
 Sheerstrakes **good**  
 Topsides **good**  
 Wales **good**  
 Plank (Bottom) and Counter **good**  
 Engine Room Skylights **✓** Coal Bunkers, Openings, Lids, &c. **✓** Scuppers **good** Cargo and Main Hatchways **good** Hatches **good**  
 General Observations, Opinion as to Class, &c. **Surveyed with ballast on board. Bottom scraped and painted. This ship is in good condition and is eligible in my opinion to remain as classed Reg 100 A.1.**

Committee's Minute **5th June, 1877**  
 Character assigned **100 A.1.**  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **✓** Paid **18**