

No. 37 Survey held at Liverpool Date Apr. 20th - 23rd 1877
 on the Ship "Edithlock" Master D. Phillips
 Tonnage 1264 Built at P. Glasgow When built 1874 - 12 mo.
 By whom built Duncan Owners J. O. Hunter & Co.
 Port belonging to Greenock Destined Voyage Calcutta -
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock.

Last Survey, No. 14137 Port of Iron Classed 100 AI 3.75.

The present Condition of the

	<u>Good</u>	<u>Greenails</u>	<u>Rivets</u>	<u>Good</u>		<u>Good</u>
Decks					Windlass and Capstan	
Waterways	✓		<u>Breasthooks and Stems</u>	✓	Pumps	✓
Comings	✓		<u>Transoms, Pointers, and Crutches</u>	✓	Boats	✓
Upper Deck Beams & Fastenings	✓		<u>Timbers of the Frame at the Openings</u>	✓	Masts, Yards, &c.	✓
Lower Deck Beams & Fastenings	✓		<u>Ditto ditto at other places</u>	✓	Sails	✓
Planksheers	✓		<u>Keelsons</u>	✓	Anchors, No. of <u>3B - 1S - 2K</u>	
Sheerstrakes	✓		<u>Clamps and Shelves</u>		Cables <u>part seen</u>	} <u>Good</u> <u>and</u>
Topsides	✓		<u>Ceiling</u>	✓	Hawsers and Warps	
Wales	✓		<u>Rudder</u>	✓	Standing and Running Rigging	} <u>Sufficient</u>
Plank (Bottom) and Counter	✓		<u>Copper</u> <u>Cement</u> When put on <u>74</u>			

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good.

Bottom sighted, cleaned and coated with paint -
This vessel being now in a good and efficient condition
is eligible in my opinion to remain as Classed -

Committee's Minute Liverpool May 25th 1877

Character assigned 100 AI. R. Brown

© 2019
J. Shilston
 Lloyd's Register
 Foundation
 Certificate (if required).

"Kasdale"

"Cairloch" 25549

18548 I



© 2019

Lloyd's Register
Foundation