

1864  
**REPORT of SURVEY for REPAIRS, &c.**

No. in Reg. Book. **No. 3012** Survey held at **Aberdeen** Date, first Survey **May 21<sup>st</sup>** Last Survey **May 29<sup>th</sup>** 18**77**  
**142** on the **Dee** Iron S.S. Master **D. Wallace**

Official Number **55228**  
TONNAGE under Tonnage Deck **262**  
Ditto of Spar Deck, or Awning Deck  
Ditto of Poop  
Ditto of Raised Qr. Dk.  
Ditto of Houses on Deck  
Ditto of Forecastle  
Gross Tonnage **304**  
Crew Space, as per Rule  
Register Tonnage, cut on Beam  
Engine Room  
Reg. Tons as St<sup>r</sup>mer, cut on Bm. **195**  
Built at **Aberdeen** When built **1843**  
Owners **Adam & Co** Port belonging to **Aberdeen**  
Residence **Aberdeen**  
By whom built **James A. Hall & Co** Destined Voyage **Coasting**  
If Surveyed Afloat or in Dry Dock **On a patent slip**  
Length of Poop **18** ft. Ditto, Forecastle **4** ft. Ditto, Raised Quarter Deck **1** ft. Years assigned. **20** Character in Register Book. **1**

Last Survey, No. **1876** Port **Iron**

REPAIRS, OR EXAMINATION AS PER RULE

*for Damage from striking Quay entering this Port*  
*Revised. 60 Plates on bows. straightened stem.*

Present Condition of the

Decks **Good**

Waterways **"**

Comings **"**

Upper Deck Beams & Fastenings **"**

Lower Deck Beams & Fastenings **"**

Planksheers **"**

Sheerstrakes **"**

Topsides **"**

Wales **"**

Plank (Bottom) and Counter **"**

Engine Room Skylights **Good** Coal Bunker, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**

General Observations, Opinion as to Class, &c. **This vessel is now in good and efficient condition and is eligible in my opinion to remain as classed**

**Good**

The Amount of Entry Fee ... £ - : - received by me, **J. W. Little**

Special **72** ... £ 2 : 2 : 0 June 10 1877

Certificate (if required) ... £ - : -

(Travelling Expenses, if any, £ **none**)

Committee's Minute **19th June, 1877**

Character assigned **Good**

**22 Gross tonnage - How made up**

**231**

Windlass and Capstan **Good**

Pumps **in efficient**

Boats **good**

Masts, Yards, &c. **"**

Condition, how ascertained **in examination and enquiry**

Sails **Good**

Anchors No. of **2 Bower & Stream & Kedge**

Cables **Good**

Hawsers and Warps **"**

Standing & Running Rigging **"**

**Good**

**Good**

**Good**

**Good**

**Good**

**Good**

**Good**

**Good**

**Good**

**Good**

**Good**

**Good**

**Good**

**Good**

**Good**

**Good**

**Good**

**Good**

**Good**

**Good**



© 2019

Lloyd's Register Foundation

IRON472-0315