

ANNUAL SURVEYS.

No. in Reg. Book. No. 12609 Survey held at Newcastle Date, first Survey 4th June Last Survey 20th June 1877
 on the Iron S. S. "Horton" Master
 Tonnage 326 Built at Sunderland When built 1872 11 Mo
 By whom built Blumer Owners H. Philipson
 Port belonging to Newcastle Destined Voyage Coasting
 Surveyed Afloat or in Dry Dock Clelands Ship

Last Survey, No. *16453 Port of Iron
 Present Condition of the
 Decks Good Greenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " ~~Timbers of the Frame at the Openings~~ "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
~~Plank~~ (Bottom) and Counter " Copper or V.M. paint When put on new
 Caulking of Good
 Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

Bottom sighted, cleaned and painted.
She is now in good & efficient condition, and eligible to remain
as classed.

Committee's Minute

26th June, 1877.

Character assigned

80 A 1

T. Moverly

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid 18

No. in Reg. Book. No. 13609 Survey held at Newcastle Date, first Survey 4th June Last Survey 20th June 1877
 on the Iron S. S. "Brazilian" Master A. Pinto Jr
 Tonnage 385 Built at Newcastle When built 1869 6 Mo
 By whom built Mitchell Owners H. Clapham & Co
 Port belonging to Newcastle Destined Voyage
 Surveyed Afloat or in Dry Dock Wallend Ship

Last Survey, No. 14329 Port of Newcastle Iron
 Present Condition of the
 Decks Good Greenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " ~~Timbers of the Frame at the Openings~~ "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
~~Plank~~ (Bottom) and Counter " Copper or V.M. paint When put on new
 Caulking of Good
 Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

Bottom sighted, cleaned and painted.
She is now in good and efficient condition, and eligible to remain
as classed.

Committee's Minute

26th June, 1877.

Character assigned

90 A 1

T. Moverly

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid 18

IRON 472-0327