

18712  
**REPORT of SURVEY for REPAIRS, &c.**

No. in Reg. Book. **No. 4482** Survey held at **Glasgow** Date, first Survey **14 May** Last Survey **25 May** 18**77**.  
on the **S.S. Amarafrica** Master **Stuart**  
TONNAGE under Tonnage Deck **2427** Built at **Greenock** When built **1874-7**  
Ditto of Spar Deck, or Awning Deck  
Ditto of Poop  
Ditto of Raised Qr. Dk.  
Ditto of Houses on Deck  
Ditto of Forecastle  
Gross Tonnage **2464** Owners **British & Colonial Steam, Nav. Co. Ltd.** Port belonging to **Glasgow**  
Crew Space, as per Rule  
Register Tonnage, cut on Beam  
Engine Room  
Reg. Tons as Stmer, cut on Bm. **1619** Residence **15 St Vincent Row Glasgow**  
By whom built **Scott** Destined Voyage **Rangoon**  
Surveyed Afloat **or** in Dry Dock **D. Henderson 16th Dry Dock**  
Length of Poop **ft.** Ditto, Forecastle **ft.** Ditto, Raised Quarter Deck **ft.** Years assigned. **Classed** **100A.1**  
Last Survey, No. **13967** Port **Iron** Character in Register Book. **2-75**

REPAIRS, OR EXAMINATION AS PER RULE

*Damage Repairs*

*Two garboard strake plates & five bottom plates on Starboard side forward removed set fair and replaced. three floor plates, three reversed frames and two frames repaired. all the ceiling hatches in main hold lifted, timbers cleared, cement repaired, and floor plates coated with thin cement. The bottom cleaned and painted.*

Cause of Repairs to be clearly stated.

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

*Good*

*Greenails*

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

*Ditto* *Ditto* at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

*Copper* *Cement* When put on **1874**

Caulking of

Bottom, Deck, & Waterways

*Good*

*Good*

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging *Sufficient*

Cargo and Main Hatchways *Good* Hatches *Good*

*This vessel is now in good condition and in my opinion capable to remain as classed*

The Amount of Entry Fee ... £ 3 : " : " received by me, *James*

Special ... £ " : " : " June 1877

Certificate (if required) ... £ " : " : " Accounted for in June

(Travelling Expenses, if any, £ )

Committee's Minute

Character assigned

10th July, 1877

*100A.1*  
*TRW Sep 77*

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON472-0403