

ANNUAL SURVEYS.

36324

Read 27.6.77

No. 1452

Survey held at London

Date 14 June 1877

S. "Crusader"

Master Davies

Tonnage 158, 158, 486 Built at Glasgow

When built 1865 3 mo

By whom built Connell

Owners Shaw, Savill & Co

Port belonging to Glasgow

Destined Voyage New Zealand

If Surveyed Afloat or in Dry Dock

Commercial dry dock

Last Survey, No. 15213 Port of Lion

Classed *A.1. 1075
S.S. 153-75

The present Condition of the

Decks	Good	Timber Rivets	Good	Windlass and Capstan	Good
Waterways		Breasthooks and Stemson	---	Pumps	---
Comings		Transoms, Pointers, and Crutches	---	Boats	5 N. ---
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings	---	Masts, Yards, &c.	---
Lower Deck Beams & Fastenings	Good	Ditto ditto at other places	---	Sails	Good
Planksheers		Keelsons	---	Anchors, No. of	3 B - 1 S - 2 K
Sheerstrakes		Clamps and Shelves	---	Cables	Good
Topsides		Ceiling	---	Hawsers and Warps	---
Wales		Rudder	---	Standing and Running Rigging	---
Plank (Bottom) and Counter		Copper Paint When put on	now		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

This ship was surveyed with ballast on board. She appeared to be in good condition and is eligible in my opinion to remain as classed viz *A.1.

Committee's Minute 3rd July, 1877.

Character assigned

*A.1

DPW

J. W. Seallard
Surveyor to Lloyd's Register

Certificate (if required).

No. 804

Survey held at London

Date 20 June 1877

S. "Matara"

Master Horn

Tonnage 853, 893, 841 Built at Glasgow

When built 1868 - 12 mo

By whom built Aitken

Owners New Zealand Shipping Co

Port belonging to London

Destined Voyage

If Surveyed Afloat or in Dry Dock

Canal dry dock

Last Survey, No. 16658 Port of Lion

Classed *A.1. 676
S.S. Low N-1-73

The present Condition of the

Decks	Good	Timber Rivets	Good	Windlass and Capstan	Good
Waterways		Breasthooks and Stemson	---	Pumps	---
Comings		Transoms, Pointers, and Crutches	---	Boats	5 N. ---
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings	---	Masts, Yards, &c.	---
Lower Deck Beams & Fastenings	Good	Ditto ditto at other places	---	Sails	---
Planksheers		Keelsons	---	Anchors, No. of	3 B - 1 S - 2 K
Sheerstrakes		Clamps and Shelves	---	Cables	Good
Topsides		Ceiling	---	Hawsers and Warps	---
Wales		Rudder	---	Standing and Running Rigging	---
Plank (Bottom) and Counter		Copper Paint When put on	now		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Surveyed with ballast on board. Rudder unshipped and lashed. This ship is in good condition and eligible in my opinion to remain as classed viz *A.1.

Committee's Minute 3rd July, 1877.

Character assigned

*A.1

DPW

J. W. Seallard
Surveyor to Lloyd's Register
Certificate (if required).