

No. 18752

Survey held at London Date, first Survey 27 June Last Survey 27 June 1877

No. in Reg. Book

on the S.S. "Elaine"

Master Hunter

237

Tonnage 343

Built at Belfast

When built 1869

2 mo.

By whom built Harland

Owners Howner

Port belonging to London

Destined Voyage

If Surveyed Afloat or in Dry Dock

Recent dry dock

Last Survey, No. 12664 Port of Iron

Classed

Years assigned. Character in Register Book. 40 A 10.76 P.S. 181.75

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Ironails Rivets Breasthooks and Stemson Transoms, Pointers, and Crutches Timbers of the Frame at the Openings Ditto ditto at other places Keelsons Clamps and Shelves Ceiling Rudder Copper K.M. When put on Caulking of Bottom, Deck, & Waterways

Windlass and Capstan Pumps Boats Masts, Yards, &c. Condition, how ascertained Sails Anchors, No. of Cables Hawser and Warps Standing and Running Rigging

Good

Good

Good and complete

Coal Bunkers, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

as classed.

This vessel appears eligible to remain as classed. Bottom repaired.

Committee's Minute

10th July, 1877.

J. Cougdo

Surveyor to Lloyd's Register of British and Foreign Shipping.

Character assigned

Certificate (if required) Paid

90 A 10.76

Lloyd's Register Foundation

180N472-0458

Dunedin

Elaine



© 2019

Lloyd's Register
Foundation