

ANNUAL SURVEYS.

18758
 No. in Reg. Book. **376** No. **16542** Survey held at **London** Date, first Survey **20th June** Last Survey **20th June** 18**77**
 on the **"S. H. Lance"** Master **Barnett**
 Tonnage **887** Built at **Sunderland** When built **1869** 10 mo.
 By whom built **Watson** Owners **Pellier**
 Port belonging to **London** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Linehouse dock**

Last Survey, No. **16542** Port of **London** Classed **X/A 1 6.76**
 Present Condition of the Decks **Good**
 Waterways **Good**
 Comings **Good**
 Upper Deck Beams & Fastenings **Good**
 Lower Deck Beams & Fastenings **Good**
 Planksheers **Good**
 Sheerstrakes **Good**
 Topsides **Good**
 Wales **Good**
 Plank (Bottom) and Counter **Good**
 Engine Room Skylights **Good**
 Coal Bunker, Openings, Lids, &c. **Good**
 Scuppers **Good**
 Cargo and Main Hatchways **Good**
 Hatches **Good**
 General Observations, Opinion as to Class, &c. **Good**
 Transoms, Pointers, and Crutches **Good**
 Timbers of the Frame at the Openings **Good**
 Ditto ditto at other places **Good**
 Keelsons **Good**
 Clamps and Shelves **Good**
 Ceiling **Good**
 Rudder **Good**
 Copper or V.M. **Good** When put on
 Caulking of Bottom, Deck, & Waterways **Good**
 Windlass and Capstan **Good**
 Pumps **Good**
 Boats **Good**
 Masts, Yards, &c. **Good**
 Condition, how ascertained **Good**
 Sails **Good**
 Anchors, No. of **Good**
 Cables **Good**
 Hawser and Warps **Good**
 Standing and Running Rigging **Good**

Bottom cleaned and recoated. This ship appears in good condition and eligible to remain as classed

Committee's Minute **10th July, 1877**
 Character assigned **X/A 1 6.76**
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid 18**

No. in Reg. Book. **981** No. **16119** Survey held at **London** Date, first Survey **22nd June** Last Survey **26th June** 18**77**
 on the **"Clyde Vale"** Master **Williams**
 Tonnage **474** Built at **Glasgow** When built **1868** 9 mo.
 By whom built **Stephen** Owners **Wylie &**
 Port belonging to **Glasgow** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Linehouse dock**

Last Survey, No. **16119** Port of **London** Classed **X/A 1 3.76**
 Present Condition of the Decks **Good**
 Waterways **Good**
 Comings **Good**
 Upper Deck Beams & Fastenings **Good**
 Lower Deck Beams & Fastenings **Good**
 Planksheers **Good**
 Sheerstrakes **Good**
 Topsides **Good**
 Wales **Good**
 Plank (Bottom) and Counter **Good**
 Engine Room Skylights **Good**
 Coal Bunkers, Openings, Lids, &c. **Good**
 Scuppers **Good**
 Cargo and Main Hatchways **Good**
 Hatches **Good**
 General Observations, Opinion as to Class, &c. **Good**
 Transoms, Pointers, and Crutches **Good**
 Timbers of the Frame at the Openings **Good**
 Ditto ditto at other places **Good**
 Keelsons **Good**
 Clamps and Shelves **Good**
 Ceiling **Good**
 Rudder **Good**
 Copper or V.M. **Good** When put on
 Caulking of Bottom, Deck, & Waterways **Good**
 Windlass and Capstan **Good**
 Pumps **Good**
 Boats **Good**
 Masts, Yards, &c. **Good**
 Condition, how ascertained **Good**
 Sails **Good**
 Anchors, No. of **Good**
 Cables **Good**
 Hawser and Warps **Good**
 Standing and Running Rigging **Good**

Bottom cleaned and recoated. Rudder painted. This vessel appears entitled to remain as classed. Surveyed with chalk ballast in main hold.

Committee's Minute **10th July, 1877**
 Character assigned **X/A 1 3.76**
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid 18**

Glance
Clyde Vale



© 2019

Lloyd's Register
Foundation