

# ANNUAL SURVEYS.

22nd

77.

No. in Reg. Book. 436 No. 16643 Survey held at London Date, first Survey 9/6/77 Last Survey 11 June 18 77  
 on the S. Rodney Master A. Lintitt  
 Tonnage 1447 Built at Sunderland When built 1844 3 mo  
 By whom built Pile Owners Devitt & Moore  
 Port belonging to London Destined Voyage  
 If Surveyed Afloat or in Dry Dock Princes Dry Dock

Last Survey, No. 16643 Port of Iron Classed 100 A 1  
 Present Condition of the Decks Good Rivets Good  
 Waterways Good Breasthooks and Stemson Good  
 Comings Good Transoms, Pointers, and Crutches Good  
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings where  
 Lower Deck Beams & Fastenings Good Ditto ditto at other places seen  
 Planksheers Good Keelsons Good  
 Sheerstrakes Good Clamps and Shelves Good  
 Topsides Good Ceiling Good  
 Wakes Good Rudder Good  
 Plank (Bottom) and Counter Good Copper or V.M. Good When put on how  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

*She is now in a good and efficient condition and eligible in my opinion to remain as classed.*

Committee's Minute 29th June, 1877. Character assigned 100 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) Paid 18

No. in Reg. Book. 31 No. 16853 Survey held at London Date, first Survey 14/6/77 Last Survey 16 June 18 77  
 on the S. Cambulq Master A. Birnie  
 Tonnage 1567 Built at Aberdeen When built 1844 3 mo  
 By whom built Duthie Owners M. Duthie  
 Port belonging to Aberdeen Destined Voyage  
 If Surveyed Afloat or in Dry Dock Princes Dry Dock

Last Survey, No. 16853 Port of Iron Classed 100 A 1  
 Present Condition of the Decks Good Rivets Good  
 Waterways Good Breasthooks and Stemson Good  
 Comings Good Transoms, Pointers, and Crutches Good  
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings where  
 Lower Deck Beams & Fastenings Good Ditto ditto at other places seen  
 Planksheers Good Keelsons Good  
 Sheerstrakes Good Clamps and Shelves Good  
 Topsides Good Ceiling Good  
 Wakes Good Rudder Good  
 Plank (Bottom) and Counter Good Copper or V.M. Good When put on how  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

*She is now in a good and efficient condition and eligible in my opinion to remain as classed.*

Committee's Minute 29th June, 1877. Character assigned 100 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) Paid 18

120N472-0568