

18886
REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No. 4049** Survey held at **Leith** Date, first Survey **14th July** Last Survey **21st July** 1877
365 on the **Iron Ste "Johanna"** Master **Rathall Care**

Official Number **158-55**
TONNAGE under Tonnage Deck **158-55**
Ditto of Spar Deck, or Awning Deck
Ditto of Poop
Ditto of Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage **158-55**
Crew Space, as per Rule **10-18**
Register Tonnage, cut on Beam **148-37**
Engine Room
Reg. Tons as St^rmer, cut on Bm.
Built at **Llanelli** When built **1842** - **5**
Owners **G. Ross** Port belonging to **Liverpool**
Residence **23 Harrington Street, Liverpool**
By whom built **Nevill** Destined Voyage **Oporto**
If Surveyed Afloat or in Dry Dock **Dry dock & afloat**

Length of Poop **ft.** Ditto, Forecastle **ft.** Ditto, Raised Quarter Deck **ft.**
Last Survey, No. **10177** Port **Llanelli Iron** Classified **90** 5-72
Character in Register Book. **omitted**

REPAIRS, OR EXAMINATION AS PER RULE **Special Survey No. 1**

The vessel placed on blocks in dry dock. the
lumber boards and ceiling equal to one shake fore and
aft on each side removed. outside of bottom scraped
& painted with three coats of red & white lead

Present Condition of the
Decks **Good** Treennails **Good** Windlass and Capstan **Good**
Waterways **Gutter** Breasthooks and Stemson **"** Pumps **one pair hon 3**
Comings **"** Transoms, Pointers, and Crutches **"** Boats **Two**
Upper Deck Beams & Fastenings **"** Timbers of The Frame at the openings **"** Masts, Yards, &c. **"**
Lower Deck Beams & Fastenings **"** Ditto Ditto at other places **"** Condition, how ascertained **By Examⁿ**
Planksheers **"** Keelsons **"** Sails **Good**
Sheerstrakes **"** Clamps and Shelves **"** Anchors No. of **3 B. 15/16**
Topsides **"** Ceiling **"** Cables **partly seen**
Wales **"** Rudder **"** Hawsers and Warps **"**
Plank (Bottom) and Counter **"** Copper Cement When put on **1842** Standing & Running Rigging **"**
Engine Room Skylights **"** Caulking of **"** Bottom, Deck, & Waterways **Good** Cargo and Main Hatchways **Good** Hatches **Good**
Coal Bunker, Openings, Lids, &c. **"** Scuppers **Good**

General Observations, Opinion as to Class, &c. **I now in good and efficient condition
and in my opinion eligible to have her character
reentered in the Register Book and there marked S. S. Net 1877**

The Amount of Entry Fee ... £ : 10 : 0 received by me, }
Special ... £ 2 : 2 : 0 25th July 1877 }
Certificate (if required) ... £ : 2 : 6
(Travelling Expenses, if any, £)
Committee's Minute **27th July, 1877.**

Character assigned **90 A**
DRW S. S. Net 77
Surveyor to Lloyd's Register of British and Foreign Shipping.
© 2019 Lloyd's Register Foundation

Cause of Repairs to be clearly stated.

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

[3,000-9/5/76.]