

# ANNUAL SURVEYS.

1871/2  
 No. 3047 Survey held at West Hartlepool Date, first Survey 13 July Last Survey 18<sup>th</sup> July 1877  
 No. in Reg. Book on the *Sea St. "Tertia"* Master *Luthgens*  
 Tonnage *2629* Built at *West Hartlepool* When built *1871 - 11 mo*  
 By whom built *Denton* Owners *Flensburg Steved. Co.*  
 Port belonging to *Flensburg* Destined Voyage  
 If Surveyed Afloat or in Dry Dock *In Dry Dock*

Last Survey, No. *16458* Port of *Liverpool*

Present Condition of the Decks *Good*

Waterways *Good*

Comings *Good*

Upper Deck Beams & Fastenings *Good*

Lower Deck Beams & Fastenings *Good*

Planksheers

Sheerstrakes *Good*

Topsides *Good*

Wales *Good*

Plank (Bottom) and Counter *Good*

Engine Room Skylights *Good*

Coal Bunker, Openings, Lids, &c. *Good* Scuppers *Good* Cargo and Main Hatchways *Good* Hatches *Good*

General Observations, Opinion as to Class, &c. *Ship is in a good & efficient state fit for the safe conveyance of dry & perishable goods to & from all parts of the world & may in my opinion remain as now classed 90 A1*

Treenails *Good*

Breasthooks and Stenson *Good*

Transoms, Pointers, and Crutches *Good*

Timbers of the Frame at the Openings *Good*

Ditto ditto at other places *Good*

Keelsons *Good*

Clamps and Shelves

Ceiling *Good*

Rudder *Good*

Copper or Y.M. When put on

Caulking of Bottom, Deck, & Waterways *Good*

Classed

Years assigned.

Character in Register Book.

*90 A1*

*S.L. (No. 1-76)*

*5/76*

Windlass and Capstan *Good*

Pumps *Good*

Boats *Good*

Masts, Yards, &c. *Good*

Condition, how ascertained *From deck*

Sails *Good*

Anchors, No. of *3 Bowers, 1 Shot, 2 Redps*

Cables *Good*

Hawsers and Warps *7 1/2 - 7 1/2 - 5 1/2 - 4 1/2. Good*

Standing and Running Rigging *Good*

Committee's Minute

*27th July, 1877.*

Character assigned

*90 A1*

*S.P. Gladstone*  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) *Paid* 18

No. Survey held at *West Hartlepool* Date, first Survey *17<sup>th</sup> July* Last Survey *10<sup>th</sup> July* 1877  
 No. in Reg. Book on the *Sea St. "Kaieteur"* Master *Pick*  
 Tonnage *1254* Built at *Hartlepool* When built *1876 - 11 mo*  
 By whom built *Withy* Owners *Steel Young & Co.*  
 Port belonging to *London* Destined Voyage *Persian Gulf*  
 If Surveyed Afloat or in Dry Dock *In Dry Dock*

Last Survey, No. *14541* Port of *Liverpool*

Present Condition of the Decks *Good*

Waterways *"*

Comings *"*

Upper Deck Beams & Fastenings *Good*

Lower Deck Beams & Fastenings *"*

Planksheers

Sheerstrakes *Good*

Topsides *"*

Wales *"*

Plank (Bottom) and Counter *Good*

Engine Room Skylights *Good*

Coal Bunkers, Openings, Lids, &c. *Good* Scuppers *Good* Cargo and Main Hatchways *Good* Hatches *Good*

General Observations, Opinion as to Class, &c. *Bottom cleaned down & coated with two coats of paint. Is now in a good & efficient state fit for the safe conveyance of dry & perishable goods to & from all parts of the world, & may in my opinion remain as now classed 90 A1*

Treenails *Good*

Breasthooks and Stenson *"*

Transoms, Pointers, and Crutches *"*

Timbers of the Frame at the Openings *Good*

Ditto ditto at other places *"*

Keelsons *Good*

Clamps and Shelves

Ceiling *"*

Rudder *"*

Copper or Y.M. When put on

Caulking of Bottom, Deck, & Waterways *Good*

Classed

Years assigned.

Character in Register Book.

*90 A1*

*12/76*

Windlass and Capstan *Good*

Pumps *Good*

Boats *Good*

Masts, Yards, &c. *Good*

Condition, how ascertained *From deck*

Sails *Good*

Anchors, No. of *3 Bowers, 1 Shot, 2 Redps*

Cables *Good*

Hawsers and Warps *Good*

Standing and Running Rigging *Good*

Committee's Minute

*27th July, 1877.*

Character assigned

*90 A1*

*S.P. Gladstone*  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) *Paid* 18