

(Rec 22/8/33)

326 on the *S. S. Beitha* Master *W. M. M.*  
YEAR. MONTH.

Length of Poop ..... ft. Ditto, Forecastle ..... ft. Ditto, Raised Quarter Deck ..... ft. Years assigned. Character in Register Book.

*Classed*

REPAIRS, OR EXAMINATION AS PER RULE For damage.

Present Condition of the		Remarks		Present Condition of the	
Decks	Good	Transoms	Good	Windlass and Capstan	Good
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats ( 3 )	"
Upper Deck Beams & Fastenings	"	Diabers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Diabers at other places	"	Condition, how ascertained	from deck
Planksheers	"	Keelsons	"	Sails	Good & Sufficient
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of	3 15 24
Topsides	"	Ceiling	"	Cables	Good
Wales	"	Rudder	"	Hawsers and Warps	Good
Plank (Bottom) and Counter	"	Copper Cement When put on	Good	Standing & Running Rigging	Sufficient
Engine Room Skylights	Good	Caulking of		Hatches	Good
Coal Bunker. Openings. Lids. &c.	Good	Bottom, Deck, & Waterways	Good		
Scuppers	Good				
Cargo and Main Hatchways	Good				

General Observations, Opinion as to Class, &c. ....

This Vessel is now in good condition and in our opinion  
eligible to remain at Classed.

The Amount of Entry Fee ... £ 1 : 0 : 0 received by me, *£ 10*  
*Damage* Special ... £ 10 : 10 : 0 *August 1874*  
 Certificate (if required) ... £ " : " : "  
 (Travelling Expenses, if any, £ )


*Saml. Lanthorn*  
 Surveyor to Lloyd's Register of British and Foreign Ships

© 2019

Committee's Minute \_\_\_\_\_ 24th August, 1877

Character assigned \_\_\_\_\_

*JKM Sep 77*

 Lloyd's Register Foundation

RON 473-0178