

# ANNUAL SURVEYS.

No. in Reg. Book. on the **No. 25716** Survey held at **Liverpool** Date, first Survey **July 13<sup>th</sup>** Last Survey **July 17<sup>th</sup>** 18 **77**  
**899** on the **(In) "John C. Munro"** Master **Summer**  
 Tonnage **613** Built at **Sunderland** When built **1862-11-20**  
 By whom built **Laird** Owners **Killick Martin & Co**  
 Port belonging to **London** Destined Voyage **hullia via Glasgow**  
 If Surveyed Afloat or in Dry Dock **In Canning dry dock**

Last Survey, No. **16045** Port of **Liverpool** Classed **\*A 1-3-76**  
 Present Condition of the Decks **Good** **Rivets** **Good**  
 Waterways **"** Breasthooks and **"**  
 Comings **"** Transoms, **Pointers** and Crutches **"**  
 Upper Deck Beams & Fastenings **"** **Timbers** of the Frame at the Openings **"**  
 Lower Deck Beams & Fastenings **"** **Ditto** ditto at other places **"**  
 Planksheers **"** Keelsons **"**  
 Sheerstrakes **"** Clamps and Shelves **"**  
 Topsides **"** Ceiling **"**  
 Wales **"** Rudder **"**  
**Plates** (Bottom) and Counter **"** **Cop** **V.M.** **Cem** When put on **"**  
 Engine Room Skylights **"** Coal Bunker, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c.

*The bottom scraped and painted - This vessel is now in good condition and in my opinion eligible to remain as classed*

Committee's Minute **Liverpool Aug<sup>st</sup> 21<sup>st</sup>** 1877  
 Character assigned **\*A.V.**

*E. C. Wheeler*  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **"** Paid **"** 18

No. in Reg. Book. on the **No. 11084** Survey held at **Liverpool** Date, first Survey **July 13<sup>th</sup>** Last Survey **July 20<sup>th</sup>** 18 **77**  
**11084** on the **(In) "Annie Richmond"** Master **I Sharp**  
 Tonnage **694.713** Built at **Glasgow** When built **1868-4-20**  
 By whom built **Stephens** Owners **P & G Sharp**  
 Port belonging to **Liverpool** Destined Voyage **America**  
 If Surveyed Afloat or in Dry Dock **Afloat in Canning dry dock**

Last Survey, No. **16712** Port of **Liverpool** Classed **\*A 1-0-76**  
 Present Condition of the Decks **Good** **Rivets** **Good**  
 Waterways **"** Breasthooks and **"**  
 Comings **"** Transoms, **Pointers** and Crutches **"**  
 Upper Deck Beams & Fastenings **"** **Timbers** of the Frame at the Openings **"**  
 Lower Deck Beams & Fastenings **"** **Ditto** ditto at other places **"**  
 Planksheers **"** Keelsons **"**  
 Sheerstrakes **"** Clamps and Shelves **"**  
 Topsides **"** Ceiling **"**  
 Wales **"** Rudder **"**  
**Plates** (Bottom) and Counter **"** **Cop** **V.M.** **Cem** When put on **60**  
 Engine Room Skylights **"** Coal Bunkers, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c.

*The bottom scraped and painted - This vessel is now in good condition and in my opinion eligible to remain as classed*


Committee's Minute **Liverpool Aug<sup>st</sup> 21<sup>st</sup>** 1877.  
 Character assigned **\*A.V.**

*E. C. Wheeler*  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **"** Paid **"** 18



"John C. Howard"  
"Annie Richmond"

25716



© 2019  
Lloyd's Register  
Foundation