

# ANNUAL SURVEYS.

No. in Reg. Book. on the *No. 59* Survey held at *London* Date, first Survey *22 July* Last Survey *27 July* 18*77*  
*Hydon* Master *Cunning*  
 Tonnage *1188* Built at *Glasgow* When built *1841* 3 mo.  
 By whom built *Langlands & Co* Owners *Globe S. P. Co*  
 Port belonging to *London* Destined Voyage  
 If Surveyed Afloat or in Dry Dock *Fletcher's dry dock*

Last Survey, No. *17921* Port of *Iron* Classed *100 A*  
 Present Condition of the Decks  
 Waterways  
 Comings  
 Upper Deck Beams & Fastenings  
 Lower Deck Beams & Fastenings  
 Planksheers  
 Sheerstrakes  
 Topsides  
 Wales  
 Plank (Bottom) and Counter  
 Engine Room Skylights  
 General Observations, Opinion as to Class, &c.  
 Treenails  
 Breasthooks and Stemson  
 Transoms, Pointers, and Crutches  
 Timbers of the Frame at the Openings  
 Ditto ditto at other places  
 Keelsons  
 Clamps and Shelves  
 Ceiling  
 Rudder  
 Copper or Y.M. When put on  
 Caulking of Bottom, Deck, & Waterways  
 Windlass and Capstan  
 Pumps  
 Boats  
 Masts, Yards, &c.  
 Condition, how ascertained  
 Sails  
 Anchors, No. of  
 Cables  
 Hawser and Warps  
 Standing and Running Rigging  
 Hatches  
 Coal Bunker, Openings, Lids, &c.  
 Scuppers  
 Cargo and Main Hatchways

*Bottom cleaned and recoated*  
*This Vessel appears in good condition and eligible to remain as classed*

Committee's Minute *10th August, 1877.*

Character assigned *100 A*

*J. H. Cougdon*  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. in Reg. Book. on the *No. 143* Survey held at *London* Date, first Survey *27 July* Last Survey *27 July* 18*77*  
*Decapolis* Master *Shuoud*  
 Tonnage *632* Built at *Sunderland* When built *1868* 8 mo.  
 By whom built *Pile* Owners *L. B. Walker*  
 Port belonging to *London* Destined Voyage  
 If Surveyed Afloat or in Dry Dock *Limestone dock*

Last Survey, No. *16624* Port of *Iron* Classed *100 A*  
 Present Condition of the Decks  
 Waterways  
 Comings  
 Upper Deck Beams & Fastenings  
 Lower Deck Beams & Fastenings  
 Planksheers  
 Sheerstrakes  
 Topsides  
 Wales  
 Plank (Bottom) and Counter  
 Engine Room Skylights  
 General Observations, Opinion as to Class, &c.  
 Treenails  
 Breasthooks and Stemson  
 Transoms, Pointers, and Crutches  
 Timbers of the Frame at the Openings  
 Ditto ditto at other places  
 Keelsons  
 Clamps and Shelves  
 Ceiling  
 Rudder  
 Copper or Y.M. When put on  
 Caulking of Bottom, Deck, & Waterways  
 Windlass and Capstan  
 Pumps  
 Boats  
 Masts, Yards, &c.  
 Condition, how ascertained  
 Sails  
 Anchors, No. of  
 Cables  
 Hawser and Warps  
 Standing and Running Rigging  
 Hatches  
 Coal Bunkers, Openings, Lids, &c.  
 Scuppers  
 Cargo and Main Hatchways

*Bottom cleaned and recoated*  
*This Vessel appears in good condition and eligible to remain as classed*

Committee's Minute *10th August, 1877.*

Character assigned *100 A*

*J. H. Cougdon*  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18