

ANNUAL SURVEYS.

IRON 473-0233

No. in Reg. Book. on the *No. 12667* Survey held at *South Shields* Date, first Survey *6th and* Last Survey *7th August 1877*
256 Tonnage *786* Built at *Belfast* Master *H. Jack*
 By whom built *Harland* Owners *Workman Bros.*
 Port belonging to *Belfast* Destined Voyage *San Francisco*
 If Surveyed Afloat or in Dry Dock *J. Young & Co. Dock*

Last Survey, No. *16596* Port of *Newcastle upon Tyne* Classed *100A1*
 Present Condition of the
 Decks *Good.* Treenails *Rivets* *Good.*
 Waterways *do.* Breasthooks and Stemson *do.*
 Comings *do.* Transoms, Pointers, and Crutches *do.*
 Upper Deck Beams & Fastenings *do.* Timbers of the Frame at the Openings *do.*
 Lower Deck Beams & Fastenings *do.* Ditto ditto at other places *do.*
 Planksheers *do.* Keelsons *do.*
 Sheerstrakes *do.* Clamps and Shetfs *Stringers* *do.*
 Topsides *do.* Ceiling *do.*
 Wales *do.* Rudder *do.*
 Planks (Bottom) and Counter *do.* Copper or Y.M. *When put on*
 Engine Room Skylights *Coal Bunker, Openings, Lids, &c.* Scuppers *Good where tried*
 General Observations, Opinion as to Class, &c. *Good Cargo and Main Hatchways Secure Hatches Good*

Bottom now cleaned and coated. She is in good condition and eligible in my opinion to remain as classed.

Committee's Minute

Character assigned

100

14th August, 1877.

J. H. Cooke

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

No. in Reg. Book. on the *No. 12667* Survey held at *South Shields* Date, first Survey *and* Last Survey *9th August 1877*
1244 Tonnage *405* Built at *South Shields* Master *G. Penan*
634 By whom built *Readhead* Owners *Gansey & Robinson*
 Port belonging to *South Shields* Destined Voyage *Bilboa*
 If Surveyed Afloat or in Dry Dock *Afloat. Tyne Dock.*

Last Survey, No. *16423* Port of *Newcastle upon Tyne* Classed *100A1*
 Present Condition of the
 Decks *Good.* Treenails *Rivets* *Good.*
 Waterways *do.* Breasthooks and Stemson *do.*
 Comings *do.* Transoms, Pointers, and Crutches *do.*
 Upper Deck Beams & Fastenings *do.* Timbers of the Frame at the Openings *do.*
 Lower Deck Beams & Fastenings *do.* Ditto ditto at other places *do.*
 Planksheers *do.* Keelsons *do.*
 Sheerstrakes *do.* Clamps and Shetfs *Stringers* *do.*
 Topsides *do.* Ceiling *do.*
 Wales *do.* Rudder *do.*
 Planks (Bottom) and Counter *do.* Copper or Y.M. *When put on*
 Engine Room Skylights *Good* Coal Bunkers, Openings, Lids, &c. *Good* Scuppers *Good* Cargo and Main Hatchways *Secure* Hatches *Good*
 General Observations, Opinion as to Class, &c.

This vessel is in good condition, and eligible in my opinion to remain as classed.

Committee's Minute

Character assigned

100

14th August, 1877.

J. H. Cooke

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18