

# REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No. 3065** Survey held at **West Hartlepool** Date, first Survey **6 August** Last Survey **9 Aug 1877**  
 on the **Sea St. "Evelyn"** Master **E. Fleetham**  
 Tonnage under Tonnage Deck **709**  
 Ditto of Spar Deck, or Avoning Deck **230**  
 Ditto of Poop **973**  
 Ditto of Raised Qr. Dk.  
 Ditto of Houses on Deck  
 Ditto of Forecastle  
 Gross Tonnage  
 Crew Space, as per Rule  
 Register Tonnage, cut on Beam  
 Engine Room  
 Reg. Tons as St' mer, cut on Bm.

Built at **West Hartlepool** When built **1876** YEAR. MONTH. **12**  
 Owners **Lowndale Co** Port belonging to **Hartlepool**  
 Residence **Hartlepool**  
 By whom built **Gray** Destined Voyage **Baltic**  
 If Surveyed Afloat or in Dry Dock **In Dry Dock**  
 Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book. **Classed 100 A1**

Last Survey, No. **17770** Port **Iron**  
 REPAIRS, OR EXAMINATION AS PER RULE **Damage**

*S. Bow two bulk shell plates taken out, heated & re-set & repaired. Fractured frame strengthened with corresponding angle at back part. Reverse frame new at upper part. Bottom cleaned down & coated with paint & black bottomish.*

Present Condition of the  
 Decks **Good**  
 Waterways **"**  
 Comings **"**  
 Upper Deck Beams & Fastenings **Good**  
 Lower Deck Beams & Fastenings **"**  
 Planksheers  
 Sheerstrakes **Good**  
 Topsides **"**  
 Wales **"**  
 Plank (Bottom) and Counter **Good**  
 Engine Room Skylights **Good** Coal Bunker, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c. **Is now in a good & efficient state, fit for the safe conveyance of dry & perishable goods to & from all parts of the world & may in my opinion remain as classed 100 A1**

Transoms, **Good**  
 Breasthooks and Stemson **Good**  
 Transoms, Pointers, and Crutches **Good**  
 Timbers of the Frame at the openings **Good**  
 Ditto Ditto at other places **Good**  
 Keelsons **Good**  
 Clamps and Shells **Good**  
 Ceiling **Good**  
 Rudder **Good**  
 Copper **When put on**  
 Caulking of Bottom, Deck, & Waterways **Good**  
 Windlass and Capstan **Good**  
 Pumps **Good**  
 Boats **Good**  
 Masts, Yards, &c. **Good**  
 Condition, how ascertained **—**  
 Sails **Good**  
 Anchors No. of **3 Bow & Stern 2 kg**  
 Cables **Good**  
 Hawser and Warps **10 1/2 - 7. 6 1/2 - 4 Good**  
 Standing & Running Rigging **Good**

The Amount of Entry Fee **£ 2 : 2 : -** received by me, **17 Aug 1877**  
 Special **£ 2 : 2 : -**  
 Certificate (if required) **£ — : — : -**  
 (Travelling Expenses, if any, £ )

Committee's Minute **21st August, 1877**  
 Character assigned **100 A1**  
 S. J. Gladstone  
 J. W. Truocott.  
 Surveyor to Lloyd's Register of British and Foreign Shipping  
 © 2019  
 Lloyd's Register Foundation  
 IRON 473-0266