

19053 ANNUAL SURVEYS.

No. 4490 Survey held at Glasgow Date 24th to 27th July 1877
on the Ten Ship "Marlborough" Master Anderson
Tonnage 1124 Built at Glasgow When built 1876
By whom built Robt Duncan Owners J Paterson & Co
Port belonging to Glasgow Destined Voyage Alas
If Surveyed Afloat or in Dry Dock Over hawking dock

Last Survey, No. 16972 Port of Ton Classed MAA
The present Condition of the
Decks Good Treenails Good Windlass and Capstan Good
Waterways " Breasthooks and Stemson Not seen Pumps "
Comings " Transoms, Pointers, and Crutches " Boats "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings Good Masts, Yards, &c. "
Lower Deck Beams & Fastenings " Ditto ditto at other places " Sails "
Planksheers " Keelsons " Anchors, No. of 30 18 in
Sheerstrakes " Clamps and Shelves " Cables Said to be complete
Topsides " Ceiling " Hawser and Warps Good
Wales " Rudder " Standing and Running Rigging "
Plank (Bottom) and Counter " Copper Cum When put on 1876

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good & true seen
The bottom scraped and recast
the is in good and efficient condition eligible to remain
as classed MAA

Committee's Minute 7th August 1877
Character assigned 100
Certificate (if required).

No. _____ Survey held at _____ Date _____ 18____
on the _____ Master _____
Tonnage _____ Built at _____ When built _____
By whom built _____ Owners _____
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
The present Condition of the
Decks _____ Treenails _____ Windlass and Capstan _____
Waterways _____ Breasthooks and Stemson _____ Pumps _____
Comings _____ Transoms, Pointers, and Crutches _____ Boats _____
Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____ Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____ Sails _____
Planksheers _____ Keelsons _____ Anchors, No. of _____
Sheerstrakes _____ Clamps and Shelves _____ Cables _____
Topsides _____ Ceiling _____ Hawser and Warps _____
Wales _____ Rudder _____ Standing and Running Rigging _____
Plank (Bottom) and Counter _____ Copper _____ When put on _____
General Observations and Opinion, Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18____
Character assigned _____