

ANNUAL SURVEYS.

No. in Reg. Book. on the **No. 25729** Survey held at **Birkenhead** Date, first Survey **July 12th** Last Survey **Aug 7th** 1877
1173 on the **Iron B.E. "Archer"** Master **J. Middleton**
 Tonnage **765** Built at **Tunderland** When built **1876-7**
 By whom built **Thompson** Owners **P. Dredale**
 Port belonging to **Liverpool** Destined Voyage **America**
 If Surveyed Afloat or in Dry Dock **Afloat in Clover's dry dock**

Last Survey, No. **16601** Port of **Iron** Classed **100 A1-7-77**
 Present Condition of the Decks **Good**
 Waterways **"**
 Comings **"**
 Upper Deck Beams & Fastenings **"**
 Lower Deck Beams & Fastenings **"**
 Planksheers **"**
 Sheerstrakes **"**
 Topsides **"**
 Wales **"**
 Plating (Bottom) and Counter **"**
 Engine Room Skylights **"** Coal Bunker, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c.

The bottom scraped and painted - This vessel is now in good condition and in my opinion eligible to remain as classed -

Committee's Minute **Liverpool August 31st 1877**
 Character assigned **100 A1**
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **18**

No. in Reg. Book. on the **No. 23** Survey held at **Liverpool** Date, first Survey **July 17th** Last Survey **Aug 9th** 1877
 on the **Iron B.E. "Gadlys"** Master **J. Taylor**
 Tonnage **500** Built at **Glasgow** When built **1876-6**
 By whom built **Birrell** Owners **J. Prust**
 Port belonging to **Transea** Destined Voyage **America**
 If Surveyed Afloat or in Dry Dock **Afloat in Canany dry dock**

Last Survey, No. **16742** Port of **Iron** Classed **100 A1-7-77**
 Present Condition of the Decks **Good**
 Waterways **"**
 Comings **"**
 Upper Deck Beams & Fastenings **"**
 Lower Deck Beams & Fastenings **"**
 Planksheers **"**
 Sheerstrakes **"**
 Topsides **"**
 Wales **"**
 Plating (Bottom) and Counter **"**
 Engine Room Skylights **"** Coal Bunkers, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c.

The bottom scraped & painted - This vessel is now in good condition and in my opinion eligible to remain as classed -

Committee's Minute **Liverpool August 31st 1877**
 Character assigned **100 A1**
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **18**



" Archer "

" Biddle "



© 2019

Lloyd's Register
Foundation