

19110
REPORT of SURVEY for REPAIRS, &c.

No. *4104* Survey held at *Barbitt* Date, first Survey *21 July* Last Survey *3rd Augt* 18*77*
on the *"Corinna"* Master *(Sale)*

AGE under Tonnage Deck *936* Built at *Newcastle* When built *1840* MONTH. *6*
of Spar Deck, or Awning Deck
of Poop
of Raised Qr. Dk.
of Houses on Deck
of Forecastle
Tonnage *1103*
Crew Space, as per Rule
Register Tonnage, cut on Beam
Engine Room
Reg. Tons as St' mer, cut on Bm. *694*
By whom built *Palmer* Destined Voyage *Mediterranean*
If Surveyed Afloat or in Dry Dock *Mills & B Dry Dock*
Length of Poop _____ ft. Ditto, Forecastle _____ ft. Ditto, Raised Quarter Deck _____ ft. Years assigned. *100 A.1*
Last Survey, No. *3243* Port *Iron* Character in Register Book. *336*
Classed *100 A.1*
S.S. No. *154*


REPAIRS, OR EXAMINATION AS PER RULE
Placed on blocks, in Dry Dock. Bottom cleaned and coated with Paint, one plate on Port Bow, lined inside, on account of indentation, supposed by anchor. Hump plate fitted to sea chest on Port Bilge. Rudder lifted, one new pinette fitted, Braces bushed, sounding pipes, Sluices, and pumps examined & made efficient. New after length of screw shaft, and one new blade to propeller fitted. Fore topmast, and Topsail Yard renewed with Pitch Pine —

Cause of Repairs to be clearly stated.

Present Condition of the					
Decks	<i>Good</i>	<i>Greenails</i>	<i>Pivots where seen</i>	<i>Good</i>	Windlass and Capstan
Waterways	"	Breasthooks and Stemson	"	"	Pumps
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained
Planksheers	"	Keelsons	"	"	Sails
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors No. of
Topsides	<i>Plating</i>	Ceiling	"	"	Cables
Wales	"	Rudder	<i>Paint</i>	<i>When put on</i>	Hawsers and Warps
Plank (Bottom) and Counter	"	Copper	<i>Good</i>	<i>Good</i>	Standing & Running Rigging
Engine Room Skylights		Caulking of			
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways			
Scuppers					
Cargo and Main Hatchways					
Hatches					

General Observations, Opinion as to Class, &c.
The Vessel appears in good, and efficient condition, eligible to remain as classed 100 A.1

The Amount of Entry Fee ... £ : : received by me, *484*
Special ... £ *2 : 2* : *1/8* 187*7*
Certificate (if required) ... £ : :
(Travelling Expenses, if any, £)
Committee's Minute *4th September 1877.*
Character assigned *100 A.1*
JP.
Henry J. Gynell
Surveyor to Lloyd's Register of British and Foreign Shipping.



[2,000—5,877.]
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

IRON 473-0371

Corinna



© 2019

Lloyd's Register
Foundation