

# REPORT of SURVEY for REPAIRS, &c.

No. 19120 Page 17874  
 No. in Reg. Book. 66 on the "Lady Cairns" Master Johnnie  
 Survey held at London Date, first Survey 27 June Last Survey 11 August 1877  
 Tonnage under Tonnage Deck 1169 Built at Belfast When built 1869 4th MONTH.  
 Ditto of Spar Deck, or Avoing Deck  
 Ditto of Poop  
 Ditto of Raised Qr. Dk.  
 Ditto of Houses on Deck  
 Ditto of Forecastle  
 Gross Tonnage 1311  
 Crew Space, as per Rule  
 Register Tonnage, cut on Beam 1264  
 Engine Room  
 Reg. Tons as St mer, cut on Bm.

Length of Poop 27 ft. Ditto, Forecastle 27 ft. Ditto, Raised Quarter Deck 27 ft.  
 Last Survey, No. 16600 Port Bm Classed S. S. No 1-74  
 Character in Register Book. \*A. 1. 76

REPAIRS, OR EXAMINATION AS PER RULE S. S. No 2.

Vessel placed in dry dock, bottom and keel examined. Bottom scraped and re-coated with paint. Limbers and ceiling equal to three strakes lifted and cement-examined and found to be adhering firmly to the iron. Windlass examined. Cables ranged on deck.

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Blank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

This ship is in good condition, and eligible in my opinion to remain classed \*A. 1. and for S. S. No 2 to be recorded.

The Amount of Entry Fee ... £ ... received by me, as

Special ... £ 4: 4: 0 29 Aug 1877

Certificate (if required) ... £ ...

(Travelling Expenses, if any, £ ...)

Committee's Minute

31st August, 1877

Character assigned

S. S. No 2-77

J. W. Cullard  
 Surveyor to Lloyd's Register of British and Foreign Shipping.



160N 473-0387