

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No. 3869** Survey held at **West Hartlepool** Date, first Survey **17th Aug** Last Survey **27th Aug** 18**77**
429 on the **Sea No. "Wiltshire"** Master **J. Robertson**

Official Number **36437**
 TONNAGE under Tonnage Deck **325**
 Ditto of Spar Deck, or Awning Deck **534**
 Ditto of Poop **400**
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St' mer, cut on Bm.

Built at **Hartlepool** When built **1876** 9
 Owners **Steel Young & Co** Port belonging to **West Hartlepool**
 Residence **West Hartlepool**
 By whom built **Withy** Destined Voyage **Spain**
 If Surveyed Afloat or in Dry Dock **In Dry Dock 2 offish**

Length of Poop **ft.** Ditto, Forecastle **ft.** Ditto, Raised Quarter Deck **ft.** Years assigned **90 A1**
 Last Survey, No. **17919** Port **Iron** Classed **90 A1** 2/77

REPAIRS, OR EXAMINATION AS PER RULE **Damage**

how done Port bow. Three plates of sheerside & two of forecasle new, two panes new at upper part, waterway in forecasle lifted the same, raised, one ship of dark plank new, Deck painted at fore & after parts, Bottom cleaned down & coated with paint.

Present Condition of the
 Decks **Good**
 Waterways **"**
 Comings **"**
 Upper Deck Beams & Fastenings **Good**
 Lower Deck Beams & Fastenings **"**
 Planksheers
 Sheersides **Good**
 Topsides **"**
 Wales **"**
 Plank (Bottom) and Counter **Good**
 Engine Room Skylights **Good** Coal Bunker, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c. **Is now in a good & efficient state, fit for the safe conveyance of dry & perishable goods to & from all parts of the World & may in my opinion be continued as classed 90 A1**

Freemasts **Good**
 Breasthooks and Stenions **"**
 Transoms, Pointers, and Crutches **"**
 Timbers of the Frame at the openings **"**
 Ditto Ditto at other places **"**
 Keelsons **Good**
 Clamps and Shells
 Ceiling **"**
 Rudder **"**
 Copper **When put on**
 Caulking of
 Bottom, Deck, & Waterways **Good**
 Windlass and Capstan **Good**
 Pumps **Good**
 Boats **Good**
 Masts, Yards, &c. **Good**
 Condition, how ascertained **From Deck**
 Sails **Good**
 Anchors No. of **3 Rowers / Shear, 2 / 1/2**
 Cables **Good**
 Hawser and Warps **Good**
 Standing & Running Rigging **Good**

The Amount of Entry Fee ... £ **2** : 0 : 0 received by me, **S. P. Gladstone**
 Special ... £ **1** : 1 : 0 **20 Aug 1877**
 Certificate (if required) ... £ : :
 (Travelling Expenses, if any, £)
 Committee's Minute **31st August, 1877**
 Character assigned **90 A1**
DRP 77

