

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No. 4172** Survey held at **Cardiff** Date, first Survey **4th** Last Survey **7th Sept 1877**
 on the **S.S. "Africa"** (Transport) Master **Margues**
 Tonnage under Tonnage Deck **1229** Built at **Dumbarton** When built **1875** MONTH **4**
 Ditto of Spar Deck, or Avoing Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage **1463** Owners **Portuguese Govern^t** Port belonging to **Lisbon**
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St^rmer, cut on Bm. **902** Residence
 By whom built **Cenny** Destined Voyage **Lisbon & China**
 Length of Poop **ft.** Ditto, Forecastle **ft.** Ditto, Raised Quarter Deck **ft.** Years assigned. **100 A. 1** Character in Register Book. **5.35**
 Last Survey, No. **14489** Port **Iron** Classed

REPAIRS, OR EXAMINATION AS PER RULE

Placed on blocks in Dry Dock. The Bottom well scraped, cleaned, and painted with Red Lead, and Peacock's patent composition.
 Two Blades of Screwpropeller removed, and replaced by new ones.

Present Condition of the

Decks	Good	Treenails	Pivots where seen	Good	Windlass and Capstan	
Waterways	"	Breasthooks and Stenson	"	"	Pumps	
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	where seen
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	Good
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	and efficient.
Planksheers	"	Keelsons	not seen	"	Sails	
Sheerstrakes	"	Clamps and Shelves	Stringers	"	Anchors No. of	
Topsides	Plating	Ceiling	"	"	Cables	
Wales	"	Rudder	Paint	Good	Hawsers and Warps	
Plank (Bottom) and Counter	"	Copper	When put on	Good	Standing & Running Rigging	
Engine Room Skylights		Caulking of				
		Bottom, Deck, & Waterways	Good			
		Coal Bunker, Openings, Lids, &c.				
		Scuppers				
		Cargo and Main Hatchways				
		Hatches				

General Observations, Opinion as to Class, &c.

The Vessel appears in good and efficient condition, eligible to remain as classed "100 A. 1."

The Amount of Entry Fee ... £ : : received by me, **478**
 Special ... £ 2 : 2 : **19** 1877
 Certificate (if required) ... £ : 5 :
 (Travelling Expenses, if any, £)

Committee's Minute

14th September, 1877.

Character assigned

100 A. 1


Henry J. Gervell
 Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

Africa



© 2019

Lloyd's Register
Foundation