

No. 4060 Survey held at Leith Date, first Survey 24th Aug Last Survey 27th Aug 1877
 No. in on the Screw Sch^r "Annie Annle" Master H. B. Beard
 Reg. Book. 1019 Tonnage 847 Built at Stockton When built 1870 - 2 ess.
 By whom built Pearse Owners Nelson Donkin & Co.
 Port belonging to London Destined Voyage from Leith
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. *15795 Port of Liverpool Iron Classified SS. Nov 1875 Years assigned. 2.6 Character in Register Book. SOA.1

Present Condition of the Decks Good Treonails Good Breasthooks and Stemson Good
 Waterways Spouter Transoms, Pointers, and Crutches Good Windlass and Capstan Good
 Comings " Timbers of the Frames at the Openings " Pumps "
 Upper Deck Beams & Fastenings " Ditto ditto at other places " Boats 3 No
 Lower Deck Beams & Fastenings " Keelsons " Masts, Yards, &c. "
 Planksheers " Clamps and Shelves " Condition, how ascertained From Deck
 Sheerstrakes " Ceiling " Sails Good
 Topsides " Rudder " Anchors, No. of 3 B. P. 2 K
 Wales " Copper or Y.M. Cement When put on 40 ft. 1875 Cables Partly seen
 Plank (Bottom) and Counter " Caulking of Bottom, Deck, & Waterways Good Hawseers and Warps "
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Good Standing and Running Rigging "

I am now in good and efficient condition and in my opinion eligible to remain as classed

Committee's Minute 4th September 1877

Character assigned SOA.1

Surveyor to Lloyd's Register of British and Foreign Shipping. John Donkin
 Certificate (if required) PAID 18 77