

ANNUAL SURVEYS.

19192

Rev 10/9/77

No. in Reg. Book. on the **No. 4575** Survey held at **Stull** Date, first Survey **18th July** Last Survey **2nd Aug 1877**
448 on the **Iron Bt Cecilia** Master **Curwen**
 Tonnage **612** Built at **Preston** When built **1863-8mo**
 By whom built **Mackinn** Owners **Nelson H^c**
 Port belonging to **Liverpool** Destined Voyage
 If Surveyed Afloat or in Dry Dock **In Corporation graving Dock & afloat in Victoria Dock**

Last Survey, No. **16526** Port of **Liver** Classed **100A1**
 Present Condition of the Decks
 Waterways **Good** Breasthooks and Stemson **Good**
 Comings **Good** Transoms, Pointers, and Crutches **Good**
 Upper Deck Beams & Fastenings **Good** Timbers of the Frame at the Openings **Good**
 Lower Deck Beams & Fastenings **Good** Ditto ditto at other places **Good**
 Planksheers **Good** Keelsons **Good**
 Sheerstrakes **Good** Clamps and Shelves **Good**
 Topsides **Good** Ceiling **Good**
 Wales **Good** Rudder **Good**
 Plank (Bottom) and Counter **Good** Copper or V.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights **Good** Coal Bunker, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**

General Observations, Opinion as to Class, &c.
Now done Lower plating of rudder renewed Cleaned and painted outside Is eligible in my opinion to remain as classed 100A1

Committee's Minute **11th September, 1877.**
 Character assigned **100A1**
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid**

No. **—** Survey held at **Hull** Date, first Survey **16th Feb** Last Survey **30th July 1877**
 No. in Reg. Book. on the **Iron Sct St Albanian** Master **Senclair**
350 Tonnage **1021** Built at **Glasgow** When built **1855**
 By whom built **1340** Owners **Wm Brown Atkinson &c**
 Port belonging to **Hull** Destined Voyage **Baltic**
 If Surveyed Afloat or in Dry Dock **Afloat in Albert & Victoria Dock**

Last Survey, No. ***16522** Port of **Liver** Classed **90A1**
 Present Condition of the Decks
 Waterways **Good** Breasthooks and Stemson **Good**
 Comings **Good** Transoms, Pointers, and Crutches **Good**
 Upper Deck Beams & Fastenings **Good** Timbers of the Frame at the Openings **Good**
 Lower Deck Beams & Fastenings **Good** Ditto ditto at other places **Good**
 Planksheers **Good** Keelsons **Good**
 Sheerstrakes **Good** Clamps and Shelves **Good**
 Topsides **Good** Ceiling **Good**
 Wales **Good** Rudder **Good**
 Plank (Bottom) and Counter **Good** Copper or V.M. When put on
 Caulking of Bottom, Deck, & Waterways **Good**
 Engine Room Skylights **Good** Coal Bunkers, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good**

General Observations, Opinion as to Class, &c.
Plating cleaned from light water line upwards &c Is eligible in my opinion to remain as classed

Committee's Minute **11th September, 1877.**
 Character assigned **90A1**
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid**