

ANNUAL SURVEYS.

No. 25759 Survey held at Liverpool Date Aug 25th 1877.
 on the Ship "Eurynome" Master Gray
 Tonnage 1347 Built at P. Glasgow When built 1862-7
 By whom built Reid. Owners J Neap & Sons.
 Port belonging to Liverpool Destined Voyage India
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock.

Rev 26/9/77

Last Survey, No. 17271 Port of Iron

Classed A1
 S.S. Low No 3 = 75. 10.76

The present Condition of the

Decks	<u>Good</u>	<u>Trunnails</u> <u>Rivets.</u> <u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stems	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	Sails	"
Planksheers	"	Keelsons	Anchors, No. of <u>3B-15-2K</u>	
Sheerstrakes	"	Clamps and Shells	Cables <u>part seen</u> <u>Good</u>	
Topsides	"	Ceiling	Hawsers and Warps <u>and</u>	
Wales	"	Rudder	Standing and Running Rigging <u>Sufficient.</u>	
Plank (Bottom) and Counter	"	Copper Cement When put on <u>62/11/75.</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good -

Bottom sighted, & coated with paint, and the vessel being now in a good and efficient condition is eligible in my opinion to remain as Classed

Committee's Minute Liverpool Sep^r 25th 1877.

Character assigned

A1.

Mull

J. Shilston.

Certificate (if required).

No. Survey held at Liverpool Date Sep 3rd 1877.
 on the Bark "Lamaya" Master H. Lindsay.
 Tonnage 570 Built at Liverpool When built 1862-11
 By whom built Vernon Owners Balfour Williamson & Co
 Port belonging to Liverpool Destined Voyage Valparaiso.
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock.

Last Survey, No. 17427 Port of Iron

Classed *A1
 S.S. Low No 3 = 76. 8.76.

The present Condition of the

Decks	<u>Good</u>	<u>Trunnails</u> <u>Rivets.</u> <u>Good.</u>	Windlass and Capstan	<u>Good.</u>
Waterways	"	Breasthooks and Stems	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	Sails	"
Planksheers	"	Keelsons	Anchors, No. of <u>3B-15-2K</u>	
Sheerstrakes	"	Clamps and Shells	Cables <u>part seen</u> <u>Good</u>	
Topsides	"	Ceiling	Hawsers and Warps <u>and</u>	
Wales	"	Rudder	Standing and Running Rigging <u>Sufficient.</u>	
Plank (Bottom) and Counter	"	Copper Cement When put on <u>62/11/68</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good.

Bottom sighted, cleaned and coated with paint, and the vessel being now in a good and efficient condition is eligible in my opinion to remain as Classed -

Committee's Minute Liverpool Sep^r 25th 1877.

Character assigned

*A1.

Mull

J. Shilston.

Certificate (if required).

THE LLOYD'S REGISTER

Samaya 25439

"Euryprone"



© 2019
Lloyd's Register
Foundation