

# ANNUAL SURVEYS.

No. 437 Survey held at London Date, first Survey 4 Sept Last Survey 10 Sept 1877  
 on the Glendale Master W. Speck  
 Reg. Book. 437 Tonnage 1127 Built at W. Hartlepool When built 1874  
 By whom built Irvin Owners Steele, Young &  
 Port belonging to W. Hpl Destined Voyage Prague dock  
 If Surveyed Afloat or in Dry Dock

Last Survey, No. 16398 Port of Iron Classed 90 A  
 Present Condition of the Decks Good  
 Waterways de Breasthooks and Stenson de  
 Comings de Transoms, Pointers, and Crutches de Windlass and Capstan  
 Upper Deck Beams & Fastenings de Timbers of the Frame at the Openings de Pumps  
 Lower Deck Beams & Fastenings de Ditto ditto at other places de Boats  
 Planksheers de Keelsons de Masts, Yards, &c. Good  
 Sheerstrakes de Clamps and Shelves de Condition, how ascertained and  
 Topsides de Ceiling de Sails  
 Wales de Rudder de Anchors, No. of complete  
 Plank (Bottom) and Counter de Copper or F.M. When put on  
 Caulking of Bottom, Deck, & Waterways de Cables  
 Standing and Running Riggings  
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches  
 General Observations, Opinion as to Class, &c.

Bottom cleaned and recoated Rudder repaired. This vessel appears eligible to remain as classed.  
Surveyed with part Cargo in after Hold  
 Committee's Minute 18th September, 1877. Thos Congdon  
 Character assigned 90 A Shearle  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. 31 Survey held at London Date, first Survey 11 Sept Last Survey 13 Sept 1877  
 on the Umzinto Master J Nurse  
 Reg. Book. 31 Tonnage 280 Built at Sunderland When built 1871  
 By whom built Pile Owners Bullard, King & Co  
 Port belonging to London Destined Voyage  
 If Surveyed Afloat or in Dry Dock Horseferry dock

Last Survey, No. 17997 Port of Iron Classed 100 A  
 Present Condition of the Decks Good  
 Waterways Good Breasthooks and Stenson Good  
 Comings Good Transoms, Pointers, and Crutches Good  
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good  
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good  
 Planksheers Good Keelsons Good  
 Sheerstrakes Good Clamps and Shelves Good  
 Topsides Good Ceiling Good  
 Wales Good Rudder Good  
 Plank (Bottom) and Counter Good Copper or F.M. When put on  
 Caulking of Bottom, Deck, & Waterways Good  
 Standing and Running Riggings  
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches  
 General Observations, Opinion as to Class, &c.

Bottom cleaned and recoated. Rudder repaired. This vessel appears eligible to remain as classed.  
 Committee's Minute 18th September, 1877. Thos Congdon  
 Character assigned 100 A Shearle  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18



*Henry White*  
*Stent*



© 2019

Lloyd's Register  
Foundation