

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No. 14069** Survey held at **Leith** Date, first Survey **17th Sept** Last Survey **21st Sept** 1877
 572 on the **Sve Scher "Gorm"** Master **Christian Moller**
 TONNAGE under Tonnage Deck **890** Built at **Renfrew** When built **1871** - **9**
 Ditto of Spar Deck, or Arwing Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage **1133**
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St' mer, cut on Bm. **753**
 Owners **Stamship & Gorm** Port belonging to **Copenhagen**
 Residence **Copenhagen**
 By whom built **Henderson** Destined Voyage **Riga**
 If Surveyed Afloat or in Dry Dock **Dry Dock**

Length of Poop **ft.** Ditto, Forecastle **ft.** Ditto, Raised Quarter Deck **ft.** Years assigned. **90 A. 1.**
 Last Survey, No. **X 15102** Port **Renfrew** Iron **S. S. Lon Net 75** **9. 75**
 Character in Register Book.

REPAIRS, OR EXAMINATION AS PER RULE **Annual Survey**

Sighted bottom scraped & painted with two coats of black Varnish: - One indented plate removed from Strake below sheer on Starboard side aft: retolled & replaced: a few slack rivets in bottom renewed Cement & caulking relaid.

Present Condition of the									
Decks	Good	Treenails	Good	Windlass and Capstan	Good				
Waterways	"	Breasthooks and Stemson	"	Pumps	"				
Comings	"	Transoms, Pointers, and Crutches	"	Boats	4 M				
Upper Deck Beams & Fastenings	"	Timbers of The Frames at the openings	"	Masts, Yards, &c.	"				
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	From deck				
Plank sheers	"	Keelsons	"	Sails	Good				
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of	3 B. 15. 2 K				
Topsides	"	Ceiling	"	Cables	Partly seen				
Wales	"	Rudder	"	Hawsers and Warps	"				
Plank (Bottom) and Counter	"	Copper Cement When put on	1871	Standing & Running Rigging	"				
Engine Room Skylights	Good	Caulking of		Cargo and Main Hatchways	Good				
Coal Bunker, Openings, Lids, &c.	Good	Bottom, Deck, & Waterways	Good	Hatches	Good				
General Observations, Opinion as to Class, &c.	Scuppers								

Is now in good efficient condition in my opinion eligible to remain as classed.

The Amount of Entry Fee ... £ : : : received by me, }
 Special ... £ 2 : 2 : : 4th Sep 1877 }
 Certificate (if required) ... £ : : 5 : :
 (Travelling Expenses, if any, £)

Committee's Minute 25th September, 1877.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

