

ANNUAL SURVEYS.

36.285

(Regd 29.8.77)

Survey held at London Date, first Survey 10 Aug Last Survey 13 August 77
 on the R. Hinde Master Atkinson
 Tonnage 4676 Built at Newcastle When built 1864 4 mo.
 By whom built Palmer Owners L. Fenwick & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Under Keel dock

Next Survey, No. 17785 Port of Iron Classed _____
 Condition of the _____

	Ribs Breasthooks and Stenson Transoms, Pointers, and Crutches Timbers of the Frame at the Openings Ditto ditto at other places Keelsons Clamps and Shelves Ceiling Rudder Copper or Y.M. When put on Caulking of Bottom, Deck, & Waterways Coal Bunker, Openings, Lids, &c. Scuppers	Windlass and Capstan Pumps Boats Masts, Yards, &c. Condition, how ascertained Sails Anchors, No. of Cables Hawser and Warps Standing and Running Riggings Cargo and Main Hatchways Hatches
Beams & Fastenings	good	good
Beams & Fastenings	good	good
Bottom and Counter	good	good
Room Skylights	good	good

Observations, Opinion as to Class, &c.
Bottom scraped and recoated. This vessel appears eligible to remain as classed.

Committee's Minute 7th September, 1877.
 Character assigned 100A1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

Survey held at London Date, first Survey 15 Aug Last Survey 18 Aug 77
 on the Scottish Hero Master Eacham
 Tonnage 869 Built at Sunderland When built 1876 5 mo.
 By whom built Douglas Owners L. Fenwick
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Under Keel dock

Next Survey, No. 16444 Port of Iron Classed _____
 Condition of the _____

	Ribs Breasthooks and Stenson Transoms, Pointers, and Crutches Timbers of the Frame at the Openings Ditto ditto at other places Keelsons Clamps and Shelves Ceiling Rudder Copper or Y.M. When put on Caulking of Bottom, Deck, & Waterways Coal Bunkers, Openings, Lids, &c. Scuppers	Windlass and Capstan Pumps Boats Masts, Yards, &c. Condition, how ascertained Sails Anchors, No. of Cables Hawser and Warps Standing and Running Riggings Cargo and Main Hatchways Hatches
Beams & Fastenings	good	good
Beams & Fastenings	good	good
Bottom and Counter	good	good
Room Skylights	good	good

Observations, Opinion as to Class, &c.
Bottom recoated. This vessel appears eligible to remain as classed.

Committee's Minute 7th September, 1877.
 Character assigned 100A1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

J. R. Kiddle

Leather Bros



© 2019

Lloyd's Register
Foundation