

ANNUAL SURVEYS.

No. 36585 Survey held at London Date, first Survey Sept 24 Last Survey Oct 2 1877
 Reg. Book. on the SS Oceans Master _____
77 Tonnage 566 Built at Middlesbro When built 1871 SM
 By whom built Buckhouse Owners Jatham & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 17235 Port of Iron
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder Broken
 Plank (Bottom) and Counter " ~~Copper or Y.M. Coating~~ When put on None
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom Coated
She is now in good condition and entitled to remain as classed

Committee's Minute _____
 Character assigned 100A1 DPW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. _____ Survey held at London Date, first Survey Sept 25 Last Survey Oct 3 1877
 Reg. Book. on the S Lammernoor Master J. Duncan
178 Tonnage 1666 Built at Glasgow When built 1874 SM
 By whom built Reid Owners Williamson Milligan & Co
 Port belonging to Liverpool Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock on main tank in Ruching Inn

Last Survey, No. 16959 Port of Iron
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " ~~Copper or Y.M. Coating~~ When put on None
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. "
She is now in good condition and entitled to remain as classed.

Committee's Minute _____
 Character assigned 100A1 DPW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 5/ Paid 13. 10 18 _____

IRON 474-0007



© 2019

Lloyd's Register
Foundation