

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** *27* on the *S. S. "Radnorshire"* Survey held at *Londonderry* Date, first Survey *15 Aug* Last Survey *27 August 1877* Master *Thompson*

TONNAGE under Tonnage Deck *7810* Built at *Glasgow* When built *1876*

Ditto of Spar Deck, or Awning Deck
Ditto of Poop
Ditto of Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage *1838*
Crew Space, as per Rule
Register Tonnage, cut on Beam
Engine Room
Reg. Tons as St' mer, cut on Bm. *1201*

Owners *Leahurst* Port belonging to *Londonderry*
Residence
By whom built
Destined Voyage
If Surveyed Afloat or in Dry Dock *South W. I. Dock*

Length of Poop *190* ft. Ditto, Forecastle *76* ft. Ditto, Raised Quarter Deck *100* ft. Years assigned. *100 M.* Character in Register Book. *8-77*

Last Survey, No. *19076* Port *Iron*

REPAIRS, OR EXAMINATION AS PER RULE

A side port about 2 feet square has been cut in the strake of plating next the Sheerstrake, and abreast the main Hatchway on the Starboard side. The cutting of the port has been fully compensated by fitting an intercostal plate above and below the port and extending to the second frame before and abaft it. This plate being attached by Angle Irons 3x3x $\frac{1}{2}$ to the outside plating and to the frames by double Angle Irons 5x3x $\frac{1}{2}$.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <i>Good</i>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <i>and</i>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps <i>Complete</i>
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	Hatches
Scuppers		
Cargo and Main Hatchways		

General Observations, Opinion as to Class, &c.

This Vessel appears eligible to remain as classed

The Amount of Entry Fee ... £ ... : : : received by me, *21/9/77*
3/9/77 Special ... £ *2 2* : : :
Certificate (if required) ... £ ... : : :
(Travelling Expenses, if any, £)


Committee's Minute

25 September, 1877.

Character assigned

100 M.
IR

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON474-0029

Radnorshire



© 2019

Lloyd's Register
Foundation