

# ANNUAL SURVEYS.

No. in Reg. Book. **No.** 697 Survey held at London Date, first Survey 1875 Last Survey Sept 3 1877  
 on the BK Snobbad Master J F Brocklebank  
 Tonnage 615 Built at Sunderland When built 1875 2 M  
 By whom built Thompson Owners Swansea Shipping Co  
 Port belonging to Swansea Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Dry Dock Ballast in

Last Survey, No. 17304 Port of Swan Classed 100A1 10-76  
 Present Condition of the  
 Decks Good Treennails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on new  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom scraped & coated  
She is now in an efficient state of repair and entitled to remain as classed

Committee's Minute 14th September, 1877 Leithhouse Martindale  
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

No. in Reg. Book. **No.** 540 Survey held at London Date, first Survey \_\_\_\_\_ Last Survey Aug 22 1877  
 on the Ellora Master Ballingale  
 Tonnage 1131 Built at Glasgow When built 1876 5 M  
 By whom built Barclay Owners Poley & Co  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Dry Dock Ballast in

Last Survey, No. 16487 Port of Swan Classed 100A1 6-96  
 Present Condition of the  
 Decks Good Treennails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on new  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom scraped & coated  
She is now in an efficient state of repair and entitled to remain as classed

Committee's Minute 11th September, 1877 Leithhouse Martindale  
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_