

ANNUAL SURVEYS.

36.569

Recd 26.9.77

No. 132 Survey held at London Date, first Survey Sept 20th Last Survey Sept 24th 1877
 in Book. on the BM Star of the East Master Philip Conway
 Tonnage 734 Built at Glasgow When built 1876 9 mo.
 By whom built Cornell Owners E Smith
 Port belonging to Plymouth Destined Voyage _____
 If Surveyed Afloat or in Dry Dock By SK Bayn

Last Survey, No. 17178 Port of London
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways 11 Breasthooks and Stemson 11
 Comings 11 Transoms, Pointers, and Crutches 11
 Upper Deck Beams & Fastenings 11 Timbers of the Frame at the Openings 11
 Lower Deck Beams & Fastenings 11 Ditto ditto at other places 11
 Planksheers 11 Keelsons 11
 Sheerstrakes 11 Clamps and Shelves 11
 Topsides 11 Ceiling 11
 Wales 11 Rudder 11
 Plank (Bottom) and Counter 11 Copper or Y.M. Copper When put on None
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights _____ Coal Bunker, Openings, Lids, &c. _____ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. _____

Classed 100A 10.76
 Years assigned. _____ Character in Register Book. _____

She is now in good condition and entitled to remain as Classed

Committee's Minute 2nd October, 1877.
 Character assigned 100A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. 1179 Survey held at London Date, first Survey Sept 11th Last Survey _____ 1877
 in Book. on the SS Mintha Master _____
 Tonnage 505 Built at Newcastle When built 1876 12 mo.
 By whom built Mitchell Owners J Nelson & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock By SK

Last Survey, No. 17897 Port of London
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways _____ Breasthooks and Stemson 11
 Comings _____ Transoms, Pointers, and Crutches 11
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings 11
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places 11
 Planksheers _____ Keelsons 11
 Sheerstrakes _____ Clamps and Shelves 11
 Topsides _____ Ceiling 11
 Wales _____ Rudder 11
 Plank (Bottom) and Counter _____ Copper or Y.M. Copper When put on None
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. _____

Classed 100A 277
 Years assigned. _____ Character in Register Book. _____

She is now in good repair and entitled to remain as Classed
The load line is marked on the vessel.

Committee's Minute 2nd October, 1877.
 Character assigned 100A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

IRON 474-0068

Star of the East &
Mentha

18

Classed

Port of

Township

Five Books and Johnson

Travels, Johnson, and Johnson

History of the State of New York

and other papers

Johnson and Johnson

Johnson and Johnson

Johnson and Johnson

Johnson and Johnson

Johnson and Johnson

Johnson and Johnson

Johnson and Johnson

Johnson and Johnson

Johnson and Johnson

Johnson and Johnson

Johnson and Johnson

Johnson and Johnson

Johnson and Johnson

Johnson and Johnson



© 2019

Lloyd's Register
Foundation