

ANNUAL SURVEYS.

No. 19382 Survey held at London Date, first Survey 25 Oct Last Survey 26 Oct 1877
 No. in on the "Abney Tower" Master Hay & Co
 Reg. Book. 23 Tonnage 708 Built at P. Glasgow When built 1875 8 mo.
 By whom built Hamilton Owners Hay & Co
 Port belonging to Lpool Destined Voyage Princes dock
 If Surveyed Afloat or in Dry Dock

Last Survey, No. 15003 Port of Iron Classed 100 A1
 Present Condition of the
 Decks Good Keels Planks Good
 Waterways de Breasthooks and Stemson de
 Comings de Transoms, Pointers, and Crutches de
 Upper Deck Beams & Fastenings de Timbers of the Frame at the Openings de
 Lower Deck Beams & Fastenings de Ditto ditto at other places de
 Planksheers de Keelsons de
 Sheerstrakes de Clamps and Shelves de
 Topsides de Ceiling de
 Wales de Rudder de
 Plank (Bottom) and Counter de Copper or Y.M. ✓ When put on ✓
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

Bottom cleaned and recoated.
This ship appears in good condition and eligible to remain as classed.

Committee's Minute 6th November, 1877. The Congdon
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 19382 Survey held at London Date, first Survey 29 Oct Last Survey 1 Nov 1877
 No. in on the "P. Verulam" Master Evans
 Reg. Book. 116 Tonnage 334 Built at Greenwich When built 1876 2 mo.
 By whom built Scott Owners Bullard King & Co
 Port belonging to London Destined Voyage Horseferry dock
 If Surveyed Afloat or in Dry Dock

Last Survey, No. 19915 Port of Iron Classed 100 A1
 Present Condition of the
 Decks Good Keels Planks Good
 Waterways de Breasthooks and Stemson de
 Comings de Transoms, Pointers, and Crutches de
 Upper Deck Beams & Fastenings de Timbers of the Frame at the Openings de
 Lower Deck Beams & Fastenings de Ditto ditto at other places de
 Planksheers de Keelsons de
 Sheerstrakes de Clamps and Shelves de
 Topsides de Ceiling de
 Wales de Rudder de
 Plank (Bottom) and Counter de Copper or Y.M. ✓ When put on ✓
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

Bottom cleaned and recoated.
This vessel appears in good condition and eligible to remain as classed.

Committee's Minute 6th November, 1877. The Congdon
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

Sherry Town

Verulam



© 2019

Lloyd's Register
Foundation