

ANNUAL SURVEYS.

22/10/77

No. in Reg. Book. 1121 No. 2580 Survey held at Liverpool Date, first Survey Sep 2nd Last Survey Sep 23rd 1877
 on the Ship "Apelles." Master A Blackstone.
 Tonnage 1030 Built at London When built 1863-5 mo.
 By whom built Dudgeon Owners Willis & Co.
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock.

Last Survey, No. 1586 Port of Liverpool Classed S.S. Lon. N^o 3-76 - 3-76.
 Present Condition of the Decks Good Good Good
 Waterways Good Breasthooks and Stomson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Cement When put on 163.
 Engine Room Skylights Good Caulking of Bottom, Deck, & Waterways Good
 General Observations, Opinion as to Class, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good

Bottom sighted cleaned and coated with paint, and the vessel being now in a good and efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool Oct 23rd 1877
 Character assigned *A1

T. Shilston.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. in Reg. Book. 477 No. 853 Survey held at Liverpool Date, first Survey Sep 14th Last Survey Sep 20th 1877
 on the Ship Nippolyta. Master J. J. Cooper.
 Tonnage 853 Built at Glasgow When built 1856.
 By whom built J. Neale & Sons. Owners J. Neale & Sons.
 Port belonging to Liverpool Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock.

Last Survey, No. 1744 Port of Liverpool Classed S.S. N^o 2/76. 11-76.
 Present Condition of the Decks Good Good Good
 Waterways Good Breasthooks and Stomson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Cement When put on 60-1/2-1/6
 Engine Room Skylights Good Caulking of Bottom, Deck, & Waterways Good
 General Observations, Opinion as to Class, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good

Bottom sighted, cleaned and coated with paint, and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed

Committee's Minute Liverpool Oct 23rd 1877.
 Character assigned *A1

T. Shilston.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

"Apelles"

"Hippolyta" 25800



© 2019

Lloyd's Register
Foundation