

ANNUAL SURVEYS.

No. 1151 Survey held at London Date, first Survey 25/9/77 Last Survey 15 Oct 1877
 No. in on the 13 1/2 Moby Maid Master Harmond
 Reg. Book. 1151 Tonnage 837 Built at Greenock When built 1868 10 ans
 By whom built Steele Owners H. Thompson &
 Port belonging to Leith Destined Voyage
 If Surveyed Afloat or in Dry Dock Bridge Dock Dry Dock

Last Survey, No. 1151 Port of Leith Classed S.S. Liv No 2. 76. 8.76
 Present Condition of the Decks Good Good
 Waterways 2' Breasthooks and Stemson Good
 Comings 3' Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings 5' Timbers of the Frame at the Opening } where
 Lower Deck Beams & Fastenings 5' Ditto ditto at other places } seen
 Planksheers 5' Keelsons
 Sheerstrakes 5' Clamps and Shelves
 Topsides 5' Ceiling Good
 Wales 5' Rudder Good
 Plating (Bottom) and Counter 5' Copper or V.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers 5' Cargo and Main Hatchways Good Hatches 5'

General Observations, Opinion as to Class, &c.
This vessel has now been altered in rig from that of a ship to that of a barque.
She is now in a good and efficient condition and eligible in my opinion to remain as classed

Committee's Minute 30th October, 1877.
 Character assigned * A 1 MMS
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid 18

No. 50 Survey held at London Date, first Survey 18/10/77 Last Survey 19 Oct 1877
 No. in on the 13 1/2 Natal Master F. Smith
 Reg. Book. 50 Tonnage 446 Built at Aberdeen When built 1846 12 ans
 By whom built J. Hall & Co. Owners J. J. Kennie
 Port belonging to Aberdeen Destined Voyage
 If Surveyed Afloat or in Dry Dock Upper Lythie Dry Dock

Last Survey, No. 17467 Port of Leith Classed 100 A 1 12.76
 Present Condition of the Decks Good Good
 Waterways Good Breasthooks and Stemson Good
 Comings 5' Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings 5' Timbers of the Frame at the Opening } where
 Lower Deck Beams & Fastenings 5' Ditto ditto at other places } seen
 Planksheers 5' Keelsons
 Sheerstrakes 5' Clamps and Shelves
 Topsides 5' Ceiling Good
 Wales 5' Rudder Good
 Plating (Bottom) and Counter 5' Copper or V.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers 5' Cargo and Main Hatchways Good Hatches 5'

General Observations, Opinion as to Class, &c.
She is now in a good and efficient condition and eligible in my opinion to remain as classed

Committee's Minute 30th October, 1877.
 Character assigned 100 A 1 MMS.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid 18