

# ANNUAL SURVEYS.

Recd 27. 10. 77

No. in Reg. Book. 710 No. 1390 Survey held at London Date, first Survey 24 Oct Last Survey 1877  
 on the ship British Commodore Master Purdy  
 Tonnage 1390 Built at Newcastle When built 1868 - 2 mo.  
 By whom built Palmer Owners British Ship Owners Co.  
 Port belonging to Liverpool Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Millwall St Dry Dock.

Last Survey, No. 18263 Port of Liverpool Classed \_\_\_\_\_ Years assigned. \_\_\_\_\_ Character in Register Book. A1  
 Present Condition of the Decks \_\_\_\_\_  
 Waterways \_\_\_\_\_  
 Comings \_\_\_\_\_  
 Upper Deck Beams & Fastenings good  
 Lower Deck Beams & Fastenings good  
 Planksheers \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_  
 Topsides \_\_\_\_\_  
 Wales \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunker, Openings, Lids, &c. \_\_\_\_\_ Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. Bottom cleaned & recoated & rudder rebushed  
This vessel appears to be in good and efficient condition, and eligible to remain as at present classed.

Committee's Minute 2nd November, 1877.  
 Character assigned A1  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18 \_\_\_\_\_  
 No. in Reg. Book. on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_ Years assigned. \_\_\_\_\_ Character in Register Book. \_\_\_\_\_  
 Present Condition of the Decks \_\_\_\_\_  
 Waterways \_\_\_\_\_  
 Comings \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_  
 Planksheers \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_  
 Topsides \_\_\_\_\_  
 Wales \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_  
 Character assigned \_\_\_\_\_  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_