

27/10/77

19456
ANNUAL SURVEYS.

No. 25815 Survey held at Liverpool Date Oct 20th 1877
on the Ship "Hilshire" Master W. Lewis.
Tonnage 1226 Built at Liverpool When built 1876 - 8 mo.
By whom built Royden Owners Hughes & Co.
Port belonging to Liverpool Destined Voyage ✓
If Surveyed Afloat or in Dry Dock Queen's Dry Dock.

Last Survey, No. 17114 Port of Liver Classed 100 AI. 10/76

The present Condition of the

	<u>Good</u>	<u>Freenails</u>	<u>Rivets.</u>	<u>Good</u>	<u>Windlass and Capstan</u>	<u>Good</u>
Decks						
Waterways	✓		<u>Breasthooks and Stems</u>	✓	Pumps	✓
Comings	✓		<u>Transoms, Pointers, and Crutches</u>	✓	Boats	✓
Upper Deck Beams & Fastenings	✓		<u>Timbers of the Frame at the Openings</u>	✓	Masts, Yards, &c.	✓
Lower Deck Beams & Fastenings	✓		<u>Ditto ditto at other places</u>	✓	Sails	✓
Planksheers	✓		<u>Keelsons</u>	✓	Anchors, No. of <u>3 B - 1 S - 2 K</u>	
Sheerstrakes	✓		<u>Clamps and Shelves</u>		Cables <u>part seen</u>	<u>Good</u>
Topsides	✓		<u>Ceiling</u>	✓	Hawsers and Warps	<u>and</u>
Wales	✓		<u>Rudder</u>	✓	Standing and Running Rigging	<u>Sufficient</u>
Plank (Bottom) and Counter	✓		<u>Copper</u> <u>Cement</u> When put on <u>1876</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good.

Bottom sighted, cleaned and coated with paint, and the vessel being now in a good and efficient condition is eligible in my opinion to remain as Classed -

Committee's Minute Liverpool Nov: 6th 1877

Character assigned

100 AI.

T. Skilston.

Certificate (if required).

No. 216 Survey held at Liverpool Date Oct 17th 1877
on the Ship "Belle of Arvon" Master H. Thomas.
Tonnage 923 Built at Sunderland When built 1876 - 8 mo.
By whom built Osbourne Owners Thomas Griffith & Co
Port belonging to Liverpool Destined Voyage India
If Surveyed Afloat or in Dry Dock Brunswick Dry Dock.

Last Survey, No. 16839 Port of Liver Classed 100 AI.

The present Condition of the

	<u>Good</u>	<u>Freenails</u>	<u>Rivets.</u>	<u>Good</u>	<u>Windlass and Capstan</u>	<u>9.76.</u> <u>Good</u>
Decks						
Waterways	✓		<u>Breasthooks and Stems</u>	✓	Pumps	✓
Comings	✓		<u>Transoms, Pointers, and Crutches</u>	✓	Boats	✓
Upper Deck Beams & Fastenings	✓		<u>Timbers of the Frame at the Openings</u>	✓	Masts, Yards, &c.	✓
Lower Deck Beams & Fastenings	✓		<u>Ditto ditto at other places</u>	✓	Sails	✓
Planksheers	✓		<u>Keelsons</u>	✓	Anchors, No. of <u>3 B - 1 S - 2 K</u>	
Sheerstrakes	✓		<u>Clamps and Shelves</u>		Cables <u>part seen</u>	<u>Good</u>
Topsides	✓		<u>Ceiling</u>	✓	Hawsers and Warps	<u>and</u>
Wales	✓		<u>Rudder</u>	✓	Standing and Running Rigging	<u>Sufficient</u>
Plank (Bottom) and Counter	✓		<u>Copper</u> <u>Cement</u> When put on <u>1876</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good

Bottom sighted, cleaned and coated with paint & the vessel being now in a good and efficient condition is eligible in my opinion to remain as Classed -

Committee's Minute Liverpool Nov: 6th 1877

Character assigned

100 AI.

T. Skilston.

Certificate (if required).

"*Thimble*"

"*Belle of Arvon*"

25815



© 2019

Lloyd's Register
Foundation