

ANNUAL SURVEYS.

19488

No. 24 Survey held at Port Adelaide Date 20th August 1877
 on the Gate Nathan Master Pilchett
 Tonnage 275 Built at Greenock When built 1863
 By whom built Steele Owners Currice & Co
 Port belonging to Melbourne Destined Voyage Colonial
 If Surveyed Afloat or in Dry Dock Patent Slip

Last Survey, No. 16401 11/75 Port of Melbourne Iron Classed A 1
 The present Condition of the s.s. no 3-35 6.36

Decks <u>Good</u>	Treenails <u>"</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>Good</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors, No. of <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Rudder <u>"</u>	Standing and Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>"</u> When put on <u>"</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

*This vessel was on the Slip for cleaning and painting;
 I have found all portions of the Hull in good condition*

Committee's Minute 23rd October, 18 77.

Character assigned 24/10/77

Fees £ 1-11-

© 2019
 Lloyd's Register
 Surveyor to Lloyd's Register
 Certificate (if required).

IRON 474-0288