

# ANNUAL SURVEYS.

*Iron Reg Bk 357*  
 No. 4588 Survey held at Hull Date 9<sup>th</sup> June to 25<sup>th</sup> Sept 1877  
 on the Iron Steamer "Leopard" Master Hedgcock  
 Tonnage 735 Built at Hull When built 1858  
 By whom built Brownlow Owners Brownlow Marsden & Co  
 Port belonging to Hull Destined Voyage Hamburg  
 If Surveyed Afloat or in Dry Dock On Tides No 2 Slipway & afloat in Princes Dock

Last Survey, No. 14720 Port of Iron S.S. Val No 3-73 Classed \*A1  
 7.75

The present Condition of the

Decks	<i>Good when seen</i>	Freemasts <u>Work</u>	Windlass and Capstan	<i>Good when seen</i>
Waterways		Breasthooks and Stemson	Pumps	
Comings		Transoms, Pointers, and Crutches	Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings	Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places	Sails	
Planksheers		Keelsons	Anchors, No. of	
Sheerstrakes		Clamps and Shelves	Cables	
Topsides		Ceiling	Hawsers and Warps	
Wales		Rudder	Standing and Running Rigging	
Plank (Bottom) and Counter		Copper When put on		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

*Now done - Bottom cleaned and painted*  
*Is eligible in my opinion to remain as classed \*A1*

Committee's Minute 6th November, 18 77.

Character assigned \*A1

*Wm Davidson*

Certificate (if required).

*Iron Reg Bk 640*  
 No. 17410 Survey held at Grimsby & Hull Date 16<sup>th</sup> Sept to 22<sup>nd</sup> Oct 1877  
 on the Iron Steamer "Royal Crown" Master Thompson  
 Tonnage 1844 Built at Newcastle When built 1874  
 By whom built 177 Palmers & Co Owners Hall Bros  
 Port belonging to London Destined Voyage Bombay  
 If Surveyed Afloat or in Dry Dock In leaving dock at Grimsby & afloat in Victoria Dock & at Hull

Last Survey, No. 17410 Port of Iron Classed 90 A1  
 1.77

The present Condition of the

Decks	<i>Good when seen</i>	Freemasts <u>Work</u>	Windlass and Capstan	<i>Good when seen</i>
Waterways		Breasthooks and Stemson	Pumps	
Comings		Transoms, Pointers, and Crutches	Boats <u>4 in No</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings	Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places	Sails	
Planksheers		Keelsons	Anchors, No. of	
Sheerstrakes		Clamps and Shelves	Cables	
Topsides		Ceiling	Hawsers and Warps	
Wales		Rudder	Standing and Running Rigging	
Plank (Bottom) and Counter		Copper When put on		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

*Now done - Bottom cleaned & painted*  
*Is eligible in my opinion to remain as classed 90 A1*

Committee's Minute 6th November, 18 77.

Character assigned 90 A1

*Wm Davidson*

Certificate (if required).