

# ANNUAL SURVEYS.

No. in **No. 12726** Survey held at **South Shields** Date, first Survey **17<sup>th</sup>** and Last Survey **19<sup>th</sup> September 1877**  
 Reg. Book. on the **Iron S.S. "Linden"** Master **J. McDearmid**  
 Tonnage **687** Built at **Sunderland** When built **1874-5 Mo**  
 By whom built **Short** Owners **R. B. Avery**  
 Port belonging to **London** Destined Voyage  
 If Surveyed Afloat or in Dry Dock **J. Young's Dock**

Last Survey, No. **18591** Port of **Liverpool** Classed **100A1**  
 Present Condition of the  
 Decks **Good.** Treenails **Rivets** **Good.**  
 Waterways **do.** Breasthooks and Stemson **do.**  
 Comings **do.** Transoms, Pointers, and Crutches **do.**  
 Upper Deck Beams & Fastenings **do.** Timbers of the Frame at the Openings **do.**  
 Lower Deck Beams & Fastenings **do.** Ditto ditto at other places **do.**  
 Planksheers **do.** Keelsons **do.**  
 Sheerstrakes **do.** Clamps and Shells **Stringers** **do.**  
 Topsides **do.** Ceiling **do.**  
 Wales **do.** Rudder **do.**  
 Plank (Bottom) and Counter **do.** Copper or Y.M. **✓** When put on **✓**  
 Caulking of Bottom, Deck, & Waterways **Good where tried**  
 Engine Room Skylights **Good** Coal Bunker, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Secure** Hatches **Good.**  
 General Observations, Opinion as to Class, &c.

*This vessel was docked after having grounded, a few keel rivets renewed and garboards caulked in places, and the bottom cleaned and recoated. She is in good condition and eligible in my opinion to remain as classed.*

Committee's Minute **16th October, 1877.**  
 Character assigned **100A1**

*Special L. 1.1.0*  
*J. H. Cooke.*

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **Paid** **18**

No. **18591** Survey held at **Liverpool** Date, first Survey **1877** Last Survey **18**  
 Reg. Book. on the **Iron S.S. "Linden"** Master **J. McDearmid**  
 Tonnage **687** Built at **Sunderland** When built **1874-5 Mo**  
 By whom built **Short** Owners **R. B. Avery**  
 Port belonging to **London** Destined Voyage  
 If Surveyed Afloat or in Dry Dock

Last Survey, No. **18591** Port of **Liverpool** Classed **100A1**  
 Present Condition of the  
 Decks **Good.** Treenails **Rivets** **Good.**  
 Waterways **do.** Breasthooks and Stemson **do.**  
 Comings **do.** Transoms, Pointers, and Crutches **do.**  
 Upper Deck Beams & Fastenings **do.** Timbers of the Frame at the Openings **do.**  
 Lower Deck Beams & Fastenings **do.** Ditto ditto at other places **do.**  
 Planksheers **do.** Keelsons **do.**  
 Sheerstrakes **do.** Clamps and Shells **Stringers** **do.**  
 Topsides **do.** Ceiling **do.**  
 Wales **do.** Rudder **do.**  
 Plank (Bottom) and Counter **do.** Copper or Y.M. **✓** When put on **✓**  
 Caulking of Bottom, Deck, & Waterways **Good where tried**  
 Engine Room Skylights **Good** Coal Bunkers, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Secure** Hatches **Good.**  
 General Observations, Opinion as to Class, &c.

Committee's Minute **18**  
 Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **Paid** **18**

IRON474-0301