

ANNUAL SURVEYS.

No. 25797 Survey held at Liverpool Date Sep 12 1877.
 on the Ship "Marypesia" Master J. Storey
 Tonnage 1443 Built at P. Glasgow When built 1866 - 4 mo
 By whom built Reid Owners J. Keefe & Sons
 Port belonging to Liverpool Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock

Last Survey, No. 17121 Port of Liverpool Classed *A1
 S. S. Lw. No. 2-74 9.76.
 The present Condition of the
 Decks Good Iron Rivets Good Windlass and Capstan Good
 Waterways " Breasthooks and Stems " Pumps "
 Comings " Transoms, Pointers, and Crutches " Boats "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Masts, Yards, &c. "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Sails "
 Planksheers " Keelsons " Anchors, No. of 3B - 1S - 2K
 Sheerstrakes " Clamps and Shelves " Cables part seen Good
 Topsides " Ceiling " Hawsers and Warps and
 Wales " Rudder " Standing and Running Rigging Sufficient
 Plank (Bottom) and Counter " Copper Cement When put on 1866

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good
Bottom sighted, cleaned and coated with paint, and
the vessel being now in a good and efficient condition
is eligible in my opinion to remain as Classed -

Committee's Minute Liverpool Oct 23 1877

Character assigned *A1

J. Skilston

Certificate (if required).

No. 94 Survey held at Liverpool Date Aug 25 1877.
 on the Bark "Garland" Master O. Lindberg
 Tonnage 599 Built at Liverpool When built 1865 - 1 mo
 By whom built Evans Owners S. Johnston & Co
 Port belonging to Liverpool Destined Voyage Buenos Ayres
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock

Last Survey, No. 16774 Port of Liverpool Classed *A1
 S. S. Lw. No. 3-76 8.76.
 The present Condition of the
 Decks Good Iron Rivets Good Windlass and Capstan Good
 Waterways " Breasthooks and Stems " Pumps "
 Comings " Transoms, Pointers, and Crutches " Boats "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Masts, Yards, &c. "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Sails "
 Planksheers " Keelsons " Anchors, No. of 3B - 1S - 2K
 Sheerstrakes " Clamps and Shelves " Cables part seen Good
 Topsides " Ceiling " Hawsers and Warps and
 Wales " Rudder " Standing and Running Rigging Sufficient
 Plank (Bottom) and Counter " Copper Cement When put on 1865

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good
Bottom sighted, cleaned and coated with paint, and
the vessel being now in a good and efficient condition
is eligible in my opinion to remain as Classed -

Committee's Minute Liverpool Oct 23 1877

Character assigned *A1

J. Skilston

Certificate (if required).

"Marpesia"

"Garland" 25497



© 2019

Lloyd's Register
Foundation