

ANNUAL SURVEYS.

No. in Reg. Book. on the 136 No. 136 Survey held at London Date, first Survey 23/10/77 Last Survey 25/10/77 Rec 2. 11. 77
 Tonnage 249 Built at Greenock When built 1845 3 mo
 By whom built Scott Owners J. H. Goodyear
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock Limekiln Dry Dock

Last Survey, No. 17437 Port of Liverpool Classed 100 Character in Register Book. 12.46
 Present Condition of the Decks Good
 Waterways Do Transoms, Pointers, and Crutches Good
 Comings Do Timbers of the Frame at the Openings Good
 Upper Deck Beams & Fastenings Do Ditto ditto at other places where
 Lower Deck Beams & Fastenings Do Keelsons Good
 Planksheers Do Clamps and Shelves Good
 Sheerstrakes Do Ceiling Good
 Topsides Do Rudder Good
 Wales Do Copper or Y.M. Paint When put on Good
 Plank (Bottom) and Counter Do Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Do Coal Bunker, Openings, Lids, &c. Do Scuppers Do Cargo and Main Hatchways Do Hatches Do

General Observations, Opinion as to Class, &c.
 This vessel has now been put into dry dock - her bottom has been scraped and painted and the cement repaired where found defective. She is now in a good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 6th November, 1877. Character assigned 100 Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) 18

No. in Reg. Book. on the 456 No. 456 Survey held at London Date, first Survey 23/10/77 Last Survey 25 Oct 77 Rec 2. 11. 77
 Tonnage 1619 Built at Glasgow When built 1845 10 mo
 By whom built Reid Owners Williamson & Millican & Co
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock Limekiln Dry Dock

Last Survey, No. 17231 Port of Liverpool Classed 100 Character in Register Book. 12.46
 Present Condition of the Decks Good
 Waterways Do Transoms, Pointers, and Crutches Good
 Comings Do Timbers of the Frame at the Openings Good
 Upper Deck Beams & Fastenings Do Ditto ditto at other places where
 Lower Deck Beams & Fastenings Do Keelsons Good
 Planksheers Do Clamps and Shelves Good
 Sheerstrakes Do Ceiling Good
 Topsides Do Rudder Good
 Wales Do Copper or Y.M. Paint When put on Good
 Plank (Bottom) and Counter Do Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Do Coal Bunkers, Openings, Lids, &c. Do Scuppers Do Cargo and Main Hatchways Good Hatches Do

General Observations, Opinion as to Class, &c.
 She is now in a good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 6th November, 1877. Character assigned 100 Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) 18