

ANNUAL SURVEYS.

No. in Reg. Book. on the 133 No. 1280 Survey held at London Date, first Survey 6th Oct. Last Survey 27. 10. 77 1877
 Tonnage 953 Built at Glasgow When built 1873 - 11 mo.
 By whom built Lon. & Gl. S. S. Co. Ltd. Owners Globe S. S. Co. (Lim.)
 Port belonging to London Destined Voyage ✓
 If Surveyed Afloat or in Dry Dock Pontoon, Victoria dock

Last Survey, No. 16630 Port of Iron Classed 100 A1
 Present Condition of the Decks Good Treenails ✓
 Waterways ✓ Breasthooks and Stemson ✓
 Comings ✓ Transoms, Pointers, and Crutches ✓
 Upper Deck Beams & Fastenings ✓ Timbers of the Frame at the Openings Surveged
 Lower Deck Beams & Fastenings Not seen Ditto ditto at other places in
 Planksheers Good Keelsons ballast
 Sheerstrakes " Clamps and Shelves ✓
 Topsides " Ceiling ✓
 Wales " Rudder Good
 Plank (Bottom) and Counter " Copper or Y.M. ✓ When put on ✓
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches ✓
 General Observations, Opinion as to Class, &c. ✓

*The Bottom cleaned and recoated.
 This vessel appears to be in good and efficient condition, and eligible to remain as classed.*

Committee's Minute 2nd November, 1877.
 Character assigned 100 A1
Deferred 2/11/77

Edwards.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid 18

No. in Reg. Book. on the 357 No. 1664 Survey held at London Date, first Survey 20 Oct. Last Survey 1877
 Tonnage 1664 Built at Glasgow When built 1874 - 12 mo
 By whom built Elder Owners G. Gilroy
 Port belonging to Dundee Destined Voyage ✓
 If Surveyed Afloat or in Dry Dock Deptford Green Dry Dock

Last Survey, No. 13736 Port of Iron Classed 100 A1
 Present Condition of the Decks Good Treenails ✓
 Waterways " Breasthooks and Stemson Good
 Comings " Transoms, Pointers, and Crutches where
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings seen
 Lower Deck Beams & Fastenings " Ditto ditto at other places Surveged
 Planksheers " Keelsons in
 Sheerstrakes " Clamps and Shelves ballast
 Topsides " Ceiling ✓
 Wales " Rudder Good
 Plank (Bottom) and Counter " Copper or Y.M. ✓ When put on ✓
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches ✓
 General Observations, Opinion as to Class, &c. ✓

*Bottom scraped and recoated.
 This vessel appears to be in good and efficient condition, and eligible to remain as at present classed.*

Committee's Minute 2nd November, 1877.
 Character assigned 100 A1

Edwards.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid 18