ANNUAL SURVEYS.

195/8 ~~26.708~~ (Paid ~~22~~ 23.11.77)

No. _____ Survey held at London Date, first Survey 7/11/77 Last Survey 8th Novr 1877

No. in Reg. Book. 1424 on the S. S. "Athole." Master Thomson

Tonnage 993,1436,1392 Built at Glasgow When built 1870 - 6 mo

By whom built Stephen Owners J. Warrack & Co

Port belonging to Leith Destined Voyage

If Surveyed Afloat or in Dry Dock Poulsons Tic: dock

Last Survey, No. 185-57 Port of Iron

Classed — Years assigned. — Character in Register Book. 95 A.1. 5.77 S.S. Liv No 1-75

Present Condition of the Decks	Good	~~Treenails~~ Rivets	Good
Waterways	— " —	Breasthooks ~~and Stemson~~	— " —
Comings	— " —	Transoms, ~~Pointers~~, and Crutches	— " —
Upper Deck Beams & Fastenings	— " —	~~Timbers of~~ the Frame at the Openings	— " —
Lower Deck Beams & Fastenings	— " —	~~Ditto~~ ditto at other places	not seen
Planksheers	— " —	Keelsons	Good
Sheerstrakes	— " —	Clamps and Shelfs	— " —
Topsides	— " —	Ceiling	— " —
Wales	— " —	Rudder	— " —
~~Plank~~ (Bottom) and Counter	— " —	~~Copper or Y.M.~~ Paint When put on	now
		Caulking of Bottom, Deck, & Waterways	Good

Windlass and Capstan	Good
Pumps	— " —
Boats	3 No — " —
Masts, Yards, &c.	— " —
Condition, how ascertained	from deck
Sails	Good
Anchors, No. of	3 B - 1 S - 2 K
Cables	Part seen Good
Hawsers and Warps	— " —
Standing and Running Rigging	— " —

Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers — " — Cargo and Main Hatchways Good Hatches — " —

General Observations, Opinion as to Class, &c.

Surveyed in ballast. Bottom sighted - cleaned and painted. This vessel is in good condition and eligible in my opinion to remain classed 95 A.1.

Committee's Minute 27th November, 1877.

Character assigned 95 A 1

J. W. Scullard

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) _____ Paid _____ 18____

No. _____ Survey held at London Date, first Survey — Last Survey 10th Novr 1877

No. in Reg. Book. 150 on the Sew Ms. "Edinburgh Castle" Master E. Jones

Tonnage 734,2678,2624 Built at Glasgow When built 1872 - 3 mo

By whom built Napier Owners J. Currie & Co

Port belonging to London Destined Voyage Cape

If Surveyed Afloat or in Dry Dock Thames Sir dry dock

Last Survey, No. 19218 Port of Iron

Classed — Years assigned. — Character in Register Book. 100 A.1. 8.77 S.S. Iron No 1-76

Present Condition of the Decks	Good	~~Treenails~~ Rivets	Good
Waterways		Breasthooks ~~and Stemson~~	— " —
Comings		Transoms, ~~Pointers~~, and Crutches	— " —
Upper Deck Beams & Fastenings		~~Timbers of~~ the Frame at the Openings	— " —
Lower Deck Beams & Fastenings		~~Ditto~~ ditto at other places	not seen
Planksheers		Keelsons	Good
Sheerstrakes		~~Clamps and Shelfs~~	—
Topsides		Ceiling	Good
Wales		Rudder	Good
~~Plank~~ (Bottom) and Counter		~~Copper or Y.M.~~ Paint When put on	now
		Caulking of Bottom, Deck, & Waterways	Good

Windlass and Capstan	Good
Pumps	— " —
Boats	7 No — " —
Masts, Yards, &c.	— " —
Condition, how ascertained	from deck
Sails	Good
Anchors, No. of	3 B - 1 S - 2 K
Cables	Good
Hawsers and Warps	— " —
Standing and Running Rigging	— " —

Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers — " — Cargo and Main Hatchways Good Hatches — " —

General Observations, Opinion as to Class, &c. Surveyed in ballast. Bottom sighted - scraped and painted. This ship appeared to be in good condition and is eligible in my opinion to remain classed 100 A.1.

Committee's Minute 27th November, 1877.

Character assigned 100 A 1

J. W. Scullard

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) _____ Paid _____ 18____

2000—15/5/77

© 2019 Lloyd's Register Foundation
IRON474-0416