

# ANNUAL SURVEYS.

No. 2584<sup>2</sup> Survey held at Liverpool Date Nov 7<sup>th</sup> 1877.  
 on the Ship "Bay of Bengal" Master C. Jones.  
 Tonnage 1527 Built at Glasgow When built 1875 - 8 mo.  
 By whom built Elder Owners J. & E. Bullock & Co.  
 Port belonging to London Destined Voyage Rangoon.  
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock.

Last Survey, No. 13009 Port of Iron Classed 100 AI

The present Condition of the

Decks	Good	Treenails	Rivets	Good	Windlass and Capstan	Good
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails	"
Planksheers	"	Keelsons	"	"	Anchors, No. of	3B - 1S - 2K
Sheerstrakes	"	Clamps and Shells	"	"	Cables	part seen } Good
Topsides	"	Ceiling	"	"	Hawsers and Warps	and
Wales	"	Rudder	"	"	Standing and Running Rigging	Sufficient
Plank (Bottom) and Counter	"	Copper	Cement	When put on	75	Good.

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Bottom sighted, cleaned and coated with paint. The vessel is in a good and efficient condition, eligible in my opinion to remain as Classed.

Committee's Minute Liverpool Nov<sup>r</sup> 23<sup>rd</sup> 1877.

Character assigned 100 AI.

T. Shilston.

Certificate (if required).

No. Survey held at Liverpool Date Nov 6<sup>th</sup> 1877.  
 on the Ship "Derbyshire" Master J. Llewellyn  
 Tonnage 1163 Built at Liverpool When built 1863 - 2 mo.  
 By whom built Jones Owners Thomas Griffith & Co.  
 Port belonging to Liverpool Destined Voyage Melbourne  
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock.

Last Survey, No. 17241 Port of Iron Classed \* AI

The present Condition of the

Decks	Good	Treenails	Rivets	Good	Windlass and Capstan	Good
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails	"
Planksheers	"	Keelsons	"	"	Anchors, No. of	3B - 1S - 2K
Sheerstrakes	"	Clamps and Shells	"	"	Cables	part seen } Good
Topsides	"	Ceiling	"	"	Hawsers and Warps	and
Wales	"	Rudder	"	"	Standing and Running Rigging	Sufficient
Plank (Bottom) and Counter	"	Copper	Cement	When put on	pt 63 pt 71	Good.

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Bottom sighted, cleaned and coated with paint. The vessel is in a good and efficient condition eligible in my opinion to remain as Classed.

Committee's Minute Liverpool Nov<sup>r</sup> 23<sup>rd</sup> 1877.

Character assigned \* AI.

T. Shilston.

Certificate (if required).



Bay of Bengal  
Derbyshire

25842.



© 2019

Lloyd's Register  
Foundation