

ANNUAL SURVEYS.

1950-26,650

No. 403 Survey held at London Date, first Survey 30th Oct^r Last Survey 2nd Nov^r 1877
 No. in on the Reg. Book. 403 Tonnage 1084 Built at Sunderland When built 1846 8^{mo}
 By whom built W Owners E. Bates & Sons Master Christian
 Port belonging to Spool Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Bridge Dock

Last Survey, No. <u>16846</u> Port of <u>Iron</u>		Classed	Years assigned.	Character in Register Book.
			100A1	9-76
Present Condition of the Decks				
Waterways	<u>do</u>	Treenails <u>do</u>	<u>do</u>	
Comings	<u>do</u>	Breasthooks and Stemson	<u>do</u>	
Upper Deck Beams & Fastenings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	
Lower Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings	<u>do</u>	
Planksheers	<u>do</u>	Ditto ditto at other places	<u>do</u>	
Sheerstrakes	<u>do</u>	Keelsons	<u>do</u>	
Topsides	<u>do</u>	Clamps and Shelves	<u>do</u>	
Wales	<u>do</u>	Ceiling	<u>do</u>	
Plank (Bottom) and Counter	<u>do</u>	Rudder	<u>do</u>	
Engine Room Skylights	<u>do</u>	Copper or Y.M.	<u>do</u>	
Coal Bunker, Openings, Lids, &c.	<u>do</u>	When put on	<u>do</u>	
General Observations, Opinion as to Class, &c.	<u>do</u>	Caulking of Bottom, Deck, & Waterways	<u>do</u>	
		Scuppers	<u>do</u>	
		Cargo and Main Hatchways	<u>do</u>	
		Hatches	<u>do</u>	
		Windlass and Capstan	<u>do</u>	
		Pumps	<u>do</u>	
		Boats	<u>do</u>	
		Masts, Yards, &c.	<u>do</u>	
		Condition, how ascertained	<u>from deck</u>	
		Sails	<u>do</u>	
		Anchors, No. of	<u>do</u>	
		Cables	<u>do</u>	
		Hawsers and Warps	<u>do</u>	
		Standing and Running Rigging	<u>do</u>	

General Observations, Opinion as to Class, &c.
Bottom cleaned and recoated.
Fore and main topmast heads strengthened in way of Cross trees.

Committee's Minute 16th November, 1877
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. 879 Survey held at London Date, first Survey 5th Nov^r Last Survey 7th Nov^r 1877
 No. in on the Reg. Book. 879 Tonnage 761 Built at Glasgow When built 1844 2^{mo}
 By whom built Stephen Owners J. Adair Master Adair
 Port belonging to Glasgow Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Princes Dock

Last Survey, No. <u>17891</u> Port of <u>Iron</u>		Classed	Years assigned.	Character in Register Book.
			100A1	3-77
Present Condition of the Decks				
Waterways	<u>do</u>	Treenails <u>do</u>	<u>do</u>	
Comings	<u>do</u>	Breasthooks and Stemson	<u>do</u>	
Upper Deck Beams & Fastenings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	
Lower Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings	<u>do</u>	
Planksheers	<u>do</u>	Ditto ditto at other places	<u>do</u>	
Sheerstrakes	<u>do</u>	Keelsons	<u>do</u>	
Topsides	<u>do</u>	Clamps and Shelves	<u>do</u>	
Wales	<u>do</u>	Ceiling	<u>do</u>	
Plank (Bottom) and Counter	<u>do</u>	Rudder	<u>do</u>	
Engine Room Skylights	<u>do</u>	Copper or Y.M.	<u>do</u>	
Coal Bunkers, Openings, Lids, &c.	<u>do</u>	When put on	<u>do</u>	
General Observations, Opinion as to Class, &c.	<u>do</u>	Caulking of Bottom, Deck, & Waterways	<u>do</u>	
		Scuppers	<u>do</u>	
		Cargo and Main Hatchways	<u>do</u>	
		Hatches	<u>do</u>	
		Windlass and Capstan	<u>do</u>	
		Pumps	<u>do</u>	
		Boats	<u>do</u>	
		Masts, Yards, &c.	<u>do</u>	
		Condition, how ascertained	<u>from deck</u>	
		Sails	<u>well found</u>	
		Anchors, No. of	<u>3B. 14 & Kedges</u>	
		Cables	<u>complete</u>	
		Hawsers and Warps	<u>sufficient</u>	
		Standing and Running Rigging	<u>do</u>	

General Observations, Opinion as to Class, &c.
Bottom cleaned and recoated.
This ship appears in good condition and eligible to remain as classed.

Committee's Minute 16th November, 1877
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____



Photar

Surline



© 2019

Lloyd's Register
Foundation